



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 1 of 45

SECTION A: INTRODUCTION

1. PURPOSE AND SCOPE OF VENDOR QUALITY MANUAL

1.1. Purpose

- 1.1.1. The purpose of this Manual is to introduce the steps of the Quality Assurance activities to assure the quality of Perodua vehicles from Production Preparation up to Mass Production. This Manual shall serve as guidance for Vendors to prepare documents and equipments to produce parts in each step of Production stage from Production Preparation to Mass Production stage.
- 1.1.2. This Manual shall describe the communication routes of Quality Assurance activities between Perodua Auto Corporation (PCSB) and Vendors to achieve and maintain Perodua Quality requirements from the beginning of the Production Preparation until the regular Mass Production.

1.2. Scope

This Manual shall serve as part of “Sale and Purchase Agreement” between PCSB and Vendor. This manual shall cover all parts supplied to Perodua. The Rules and Procedures in this manual shall be followed by Vendors according to the steps of the Production Preparation up to the Regular Mass Production.

1.3. Definition

- 1.3.1. Regular Process Part Sample (RPPS)
First part sample are [from mass production](#) tooling, material machine and process.
- 1.3.2. Parts Matching
Quality activity to evaluate the accuracy of the Regular Process Part Samples related with Pressed Parts (P), the influences of Painting Process (T) and the accuracy of the Assembly Parts (A). Parts matching activities shall give feed back to the Vendor on the accuracy of the Regular Process Part Samples. Vendor shall do improvement until the accuracy of the part is approved by Parts Matching Team.
- 1.3.3. [Line Trial](#)
Activities conducted to check the function and workability of production equipment in the Production Line. All problems found in this event shall be resolved before shifting to the Pilot Production Stage.
- 1.3.4. Request For Design & Development of Parts (RDDP)



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 2 of 45

Sheet issued by PCSB to vendor for parts drawing and design prepared by vendor. The vendor shall submit the final drawing to PCSB using Application Sheet for Approval (ASA) and Receipt of Approval Drawing (RAD).

1.3.5. Engineering Change Request (ECR)

Sheet issued by vendor for any request for changes required in drawing, part number or technical specification.

1.3.6. Engineering Change Instruction (ECI)

Instruction sheet issued to vendor by PCSB for any changes related to [design of](#) parts.

1.3.7. Pre Study Request (PSR)

Sheet issued by PCSB to Vendor before ECI implementation. PSR shall be issue when necessary.

1.3.8. Technical Instruction Sheet (TIS)

Additional technical instructions sheet issue as a supplementary of the Drawings.

1.3.9. Pilot Production

Production process after fulfill the Pilot Production Commencement Criteria. In this activity all approved parts are involved in building a complete vehicle. If necessary PCSB shall divide 2 steps in Pilot Production Stage: the 1st Pilot Production (1PP) and the 2nd Pilot Production (2PP). All related Division shall perform their own function in the production process to identify any obstacle in the process to be improved before the Mass Production.

1.3.10. Quality Confirmation (HINKAKU)

Quality Confirmation activities before shifting to the Mass Production Stage to confirm that all Quality Targets have been achieved by the normal production processes both in the PCSB's Factory and also in the Vendor's Factory. All necessary documents and equipments shall be made available. All Limit Samples have been approved by PCSB-QA to be used in the Mass Production.

1.3.11. Mass Production

Production process after 3 month of initial Mass Production stage and all evaluation criteria fulfilled.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 3 of 45

1.3.12. SPC

Statistical Process Control

In this Manual the word “shall” indicates a requirement. The word “should” indicates a recommendation. Paragraph marked “NOTE” are for guidance in understanding or clarifying the associated requirement.

Where the term “such as” is used, any suggestion are for guidance only.

2. COORDINATION AND MANAGEMENT

PCSB Procurement & Vendor Development (PVD) Department shall coordinate and manage all activities regarding the distribution, explanation and implementation of this PCSB-Vendor Quality Manual. [PCSB-PVD Department shall communicate with related departments in PCSB in the event where any dispute occurred between PCSB-Divisions and Vendors that related with this PCSB-Vendor Quality Manual.](#)

Beside the names of the related Department that are provided in this documents, Research & Development Department (R&D), Quality Residence Engineering Department (QRE), [Quality Engineering \(QE\)](#), [Quality Parts \(QP\)](#), Production Preparation Control Division (PPC) and Quality Assurance (QA) shall serve as official contact for the Vendors.

3. VENDOR VISIT

3.1. SUPPLIER PART TRACKING TEAM (SPTT)

3.1.1. Purpose

3.1.1.1. Supplier Part Tracking Team (SPTT) is a team consists of five departments in PCSB i.e. PVD (leader), PPC, [QE/ QRE](#), R&D and Logistics for the purpose of follow up and supports the vendors in development of parts form production preparation stage until mass production stage. For this purpose the team shall conduct scheduled visit to vendors to discuss and evaluate the progress.

3.1.1.2. Purpose of these activities is to ensure quality, cost and volume in supplier mass production able to meet the requirement set by PCSB, to ensure smooth start of production in PCSB and to archive quality level required.

3.1.2. Scope

This activity shall covers localization of new developed model only. For 2nd stage localization, monitoring shall be done by PVD department.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 4 of 45

3.1.3. Vendor Responsibility

3.1.3.1. SPTT First Visit (After Drawing Arrival)

Purpose of this visit is to synchronize vendor production preparation plan with PCSB total schedule and to confirm actual tooling progress.

- 3.1.3.1.1. Vendor shall prepare finalize production preparation plan for all item including tooling development that fit with PCSB schedule.
- 3.1.3.1.2. Vendors shall prepare QA plan which include QC process chart, part inspection standard, checking fixture etc.
- 3.1.3.1.3. Vendor shall confirm the technical specification required and ensure that all technical specification is available.
- 3.1.3.1.4. Vendor shall confirm that all drawings, part numbers and RDDP were received and correct version.

3.1.3.2. SPTT 2nd Visit (During or Before Parts Delivery)

Purpose of this visit is to confirm the production preparation progress and to confirm the quality of samples parts which will be delivered for Local Part Verification Vehicle (LPVV)

- 3.1.3.2.1. Vendor shall prepare production preparation plan report indicating the actual vs. plan and tooling progress report with actual result.
- 3.1.3.2.2. Vendor shall report on problem encountered during the development in the defect flow diagram and report the remaining problem and the propose countermeasure.
- 3.1.3.2.3. Vendor shall present the inspection data using part inspection standard and update to Perodua on the quality control process chart (QCPC).
- 3.1.3.2.4. Perodua shall do plant visit to verify the progress of regular process preparation.

3.1.3.3. SPTT 3rd Visit (Before/ During PP Parts Delivery)

Purpose of this visit is to check on the production line completion for PP parts production. For this visit vendor shall prepare the listed item:

- a) Production preparation report

Vendor shall report on actual progress of part development.

- b) ECI implementation

Report on implementation of all ECI received and to verify on actual parts.

- c) LPVV problems

 Perusahaan Otomobil Kedua Sdn. Bhd.		VENDOR QUALITY MANUAL	
TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 5 of 45
Report on problem and countermeasure status using problem follow up sheet. d) Regular process Vendor shall complete the QCPC for all regular process. e) Training Vendor shall prepare the training plan and status for personnel involved in production and quality. f) Standards reference in Genba Vendor shall ensure that all standard operating procedure (SOP), work instruction, inspection standard are available. g) Quality documents Vendor shall prepare all quality document used e.g. PIS, QCPC etc. h) Production capacity Report on production capacity study in capacity study sheet. i) Packing standard/ style Report on agreed packing standard to be used and the logistic plan. j) Join trial Perodua shall participate in production trail to evaluate the readiness of vendor production line. 3.1.3.4. <u>SPTT Mass Production Trial Visit</u> Purpose of this visit is to do final confirmation of quality and production volume under the same condition as start of production a) Vendor shall set the production for one hour production run based on N-6 data form PCSB. This trial shall be jointly conducted with PCSB. b) Vendor shall check the trial parts based on PIS and verify the process capacity and process capability according to plan. Vendor shall provide statistical data including process capability result for special characteristics (∇S, ∇E, ∇R, ∇A) c) Summary of the trial shall be reported, and retrial shall be performed if major problem persist. d) Vendor shall prepare the production plan report, countermeasure status, production capacity report and initial control plan.			



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 6 of 45

3.2. PRODUCT QUALITY CONFIRMATION MEETING (PQCM) Before/ During PP

3.2.1. Purpose

- 3.2.1.1. To monitor the newly localized parts development and approval process.
- 3.2.1.2. To verify the production process and manufacturing condition of the vendors are prepared to supply the parts to PERODUA.
- 3.2.1.3. To ensure and confirm that parts that will be supplied to PERODUA meeting all specification requirements and manufacturing condition.
- 3.2.1.4. To check on the level of quality system, manufacturing process, production capacity and capability, facilities and maintenance, and the delivery system in order to ensure that the vendors shall continuously mass-produce the quality parts.

3.2.2. Scope

This procedure shall apply to audit all Localized Parts for existing models of PERODUA vehicles

3.2.3. Supplier Responsibility

- 3.2.3.1. When received PQCM notice by PCSB PVD department vendor shall submit the PQCM report to PVD department.
- 3.2.3.2. When requested, vendor shall submit and present the following document (where applicable) during the audit:
 - a) Approved and updated drawing.
 - b) Approved Part Inspection Standard (PIS).
 - c) Performance, reliability and material test report.
 - d) Approved checking fixture with complete dimensional report and drawings.
 - e) Mould pattern life data.
 - f) Approved limit sample and master sample.
 - g) Trial report (minimum of one day production/ 300 units/ as per agreement with PCSB and Vendor).
 - h) Total gross output.
 - i) Total net output.
 - j) Production efficiency vs. PCSB requirement.
 - k) Cycle time and standard time.
 - l) Machine capability Cm & Cmk.
 - m) Process capability Cp & Cpk.
 - n) Analysis of defect with graphical data.
 - o) X bar & R control chart on critical parameters.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 7 of 45

- p) Data on preventive and corrective action.
- q) Target vs. actual reject data.
- r) Dimensional product report with Pp & Ppk.
- s) Calibration system.
- t) Skill chart.
- u) Standard operating procedure (SOP) or Work Instruction Sheet (WIS).

3.2.3.3. All report shall be duly approved by vendor's management.

3.3. VENDOR AUDIT

3.3.1 Purpose

To survey the Vendor's facilities and production process, to control the vendor's quality assurance system and activities and to assist the vendor in the process development.

3.3.2. Scope

These activities are performed [annually](#) to all PCSB's vendors.

3.3.3. Definition

When necessary, PCSB shall carry out the following type of post production audit at vendor premises.

- a) Preventive Action Validation Audit
- b) PIS Verification audit
- c) Process Change Verification Audit.

3.3.4. Vendor Responsibility

- 3.3.4.1. Vendor shall facilitate PCSB to conduct the process survey assisting the vendor to improve the production line, to check the probable causes of defected parts and to check the production line if there is any modification in the process.
- 3.3.4.2. The Vendor shall comply with the items pointed out in the process survey quickly.
- 3.3.4.3. The Vendor shall also notify their sub-vendor that PCSB may accompany the vendor on the survey of the sub-vendor related with parts that are supplied to PCSB.
- 3.3.4.4. During process survey, PCSB shall review the Vendor compliance to the standard quality requirements (PIS, checking gauge, QCPC). If the Vendor is not confirming the certain state in the quality standard, PCSB shall request the Vendor to confirm some specific items from the quality standard.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 8 of 45

4. DESIGNATION OF THE VENDOR'S REPRESENTATIVE

4.1. Purpose

To build and improve communication route between PCSB and Vendor in daily operation related Divisions (PVD, QRE, **QE**, QA, **QP**, PPC, etc.) from the beginning of the Production Preparation until the Regular Mass Production.

4.2. Scope

4.2.1. PCSB-PVD department shall requests the Vendor to submit the Vendor Representative Information. The Representative shall be accessible by PCSB, Quality Control PIC, Production Preparation PIC, Day Shift PIC and Night Shift PIC.

4.2.2. The Vendor Quality Control Representative or equivalent shall be assigned as the Vendor Representative. The representative shall have an authority to manage and control the implementation of this manual, to arrange the effective flow of quality information between the Vendor and PCSB. The representative can delegates to the 1st and 2nd shift Quality Supervisor or equivalent through, the Quality Control Manager to stop non conforming parts from being shipped to PCSB, once informed by PCSB-Quality Assurance Department. The Quality Control Manager shall coordinate the Shift Quality Supervisors to maintain the quality consistency between day and night shifts production.

4.3. Vendor Responsibility

4.3.1. The Vendors shall fill and submit Vendor Representative Information to PCSB PVD Department.

4.3.2. The Vendors shall assign their Quality Assurance Representative as the Vendor Representative who shall be in charge in all quality assurance activities internally and to whom the PCSB-VQM shall be distributed.

4.3.3. The Vendor Quality Assurance Manager shall delegates the authority to shift supervisors (Separately for both day and night shift) to stop non conforming parts from being shipped to PCSB, as well as taking counter measure after coordinating with PCSB.

4.3.4. The vendor shall notify PCSB side within 10 days if there are changes in the names of the contact persons.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 9 of 45

4.3.5. The Vendor Representative shall be responsible for maintaining a current copy of the PCSB-VQM and assuring that each division of the organization are trained to follow PCSB-VQM. The vendor shall use the Vendor Representative Information Form (Attachment 1) to designate vendor contact persons

4.3.6. The Vendor Representative shall attach their organization chart to the Vendor Representative Information form when submitting the form to PCSB-PVD division

SECTION B: QUALITY SYSTEM REQUIREMENT

1. PRODUCTION PREPARATION PLAN

1.1. Purpose

- 1.1.1. To control the production preparation activities totally. To provide a schedule of total manufacturing plan, quality control activities to assure stability of part quality in the mass production stage.
- 1.1.2. To provide a periodical evaluation regarding to the production preparation items to assure the mass production start up on time.

1.2. Scope

Each part supplied to PCSB shall have a Production Preparation Plan, to show the relationship between the PCSB General Schedule and the vendor production preparation activities. The Production Preparation plan shall include:

- a) The PCSB Production Preparation General Schedule.
- b) Vendor Production Preparation Schedule.
- c) The process plan.
- d) Facility plan and other plans related with the Design, the Building, the Dies, the Jigs, and the Equipments.
- e) Schedule for selecting, evaluating their sub-vendor, sub-vendor's planning related with the raw material or the components.
- f) Schedule for preparation of Quality Assurance Plan, Inspection Plan Schedule including the Vendor's in-house Inspection Standards to assure in process quality and the final part quality, Manufacturing Quality Chart, and Checking Fixture Inspection Schedules.
- g) Vendor Production Preparation Schedule shall indicate vendor assembly trials and part shipping schedule to meet PCSB requirement. The vendor comprehensive assembly trials shall simulate the mass production process which involves the vendor's equipment, material, tooling and workmanship.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 10 of 45

- h) Packaging and Delivery system indicating timing for packaging development including design, samples, trial, approval and building plans.

1.3. Vendor Responsibility

- 1.3.1. The Vendor shall develop and submit a draft of the Production Preparation Plan (Attachment 2) with a cover letter to PCSB-PVD Division. This draft shall be submitted within two weeks after receiving the preparation drawings. This draft shall describe production preparation activities timing and date as complete as possible. This plan shall be based on the PCSB's General Schedule for the production preparation. After all related departments of the Vendor have approved the Production Preparation plan; the draft shall be discussed with the PCSB-PVD. Div and get the approval.
- 1.3.2. If necessary PCSB-PVD Division shall request to the Vendor to revise its Production Preparation Plan. The Production Preparation plan shall undergo some adjustments as the production preparation stage progresses. Any revision of the content shall be submitted to the PCSB-PVD Division.
- 1.3.3. The status of the plan shall be reviewed frequently by the Vendor. This shall become a working plan document for preparing mass production. Monthly progress report shall not be required after starting of Mass production.

2. PART INSPECTION STANDARD (PIS)

2.1. Purpose

The Part Inspection Standard defines the certain characteristics of each part including the dimensions, the appearance and performance, the method and the frequency of checking. Therefore all of parts which will be assembled shall follow the Part Inspection Standard.

2.2. Scope

- 2.2.1. The criteria of the Part Inspection Standard (PIS) shall be established referring to the drawing specifications, accuracy standard, TIS, DTS, JIS, etc.
- 2.2.2. Material specifications shall be clearly indicated in the Part Inspection Standard and also in the Part Inspection Check sheets.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 11 of 45

- 2.2.3. The Dimensions and tolerances shall follow drawing. If the drawing does not mention the tolerances, the tolerances shall follow other reference standard such as the Technical Instruction Sheet (TIS), Daihatsu Technical Standard (DTS), JIS, etc.
- 2.2.4. Performance test of the part are usually mentioned in the drawing, TIS or DTS. Frequency for testing during the mass production shall be defined in the Part Inspection Standard (PIS).
- 2.2.5. If necessary, boundary/ limit sample part shall be defined for items related to “appearance”.
- 2.2.6. Inspection Items (Sketch, Measurement, Weight, Appearance, Performance test), Inspection Method and Tool, Dimension Tolerance, Sampling Plan shall be clearly indicated in the Part Inspection Standard.

2.3. Vendor Responsibility

- 2.3.1. Vendors shall prepare the Part Inspection Standard (PIS) (Attachment 3) after receiving preparation drawing or checking fixture (CF) spec. To prepare the PIS, vendors shall refer to the drawings, TIS, DTS and other technical documents.
- 2.3.2. Vendors shall submit the original Part Inspection Standard to PCSB-QE for approval. The PIS shall be approved by first try out part (T0).
- 2.3.3. QE PCSB shall request vendors to amend the PIS if deem fit and vendor shall resubmit again after the amendment has been made. Once the Part Inspection Standard is approved, vendors shall keep the controlled copy. Should there be a dispute on the approved PIS; master copy kept by QE PCSB shall be used as a basis of primary reference. If the supplement standards or specification are not specified in the drawing, DTS or similar specification shall be use as a secondary reference. If disputes persist, R&D advice shall be taken as the tertiary reference. If not, DMC advice shall be decided as the final alternative.
- 2.3.4. Vendors shall get the approval of the PIS from PCSB-QE Department before starting trial (T0) at PCSB. Vendors shall maintain and up date PIS accordingly. The revision may be due to additional request item by PCSB QE or/and updates in technical documents. Updated PIS shall be submitted to PCSB-QE Department for approval.
- 2.3.5. Any sample submitted for evaluation during development stage shall be accompanied with approved PIS data.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 12 of 45

2.3.6. During mass production stage, vendor shall submit a complete dimensional report via approved PIS, and attached any supporting document if necessary together with duly sign declaration of compliance form, within the specified date line.

2.3.7. [PCSB QP](#) shall approve the monthly PIS data submission based on the compliance on the actual recorded data against the specification.

2.3.8. Ranking in PIS shall refer to below table:

RANKING	CATEGORY	DESCRIPTION	REMARK
Special Characteristics	Quality	- Can cause problem that may not confirm to regulations, fatal accident, or vehicle safety. - Can cause problem that may led to important qualitative defect or emission concentration failure of exhaust. - Items where regulations are applied.	Problems where it is impossible to mass produce and to ship unless countermeasures are taken Indicated in drawing ∇S, ∇E, ∇R, ∇A
	Quality	- Problem that can cause vehicle or engine cannot function. - Problem that can lead to serious breakdown or effect on performance. - Problem that occur in important function parts where frequency of operation is high - Problem that has the possibilities to get injured during operation.	Problems where it is impossible to mass produce and to ship unless countermeasures are taken
	Safety	Can cause serious problem to work environment or safety of work.	
	Ease of Operation	Problem that make fitting impossible unless countermeasures are taken or problem that affect mass production seriously (Quality/Operation rate).	
A	Facilities Machine Die	Problem that cause modification of facility / mold drastically	Problems difficulty in scheduling the facility investment
B	Ease of Operation	- Problem regarding services. - Problem that affect product values. - Other problems than A. - Problem regarding production or operate ability. - Problem that lead to improvement of specification of product.	It is impossible to mass produce and to ship on certain condition
C	Ease of Operation	Items that do not belong to S,A,B	It is impossible to mass produce and to ship



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 13 of 45

3. CHECKING FIXTURES AND CHECKING GAUGE

3.1. Purpose

- 3.1.1. To provide vendors an adequate measuring tools for measuring accurately 3 dimensional (3D) parts.
- 3.1.2. To analyze the dimensional problems regarding part fitting condition.
- 3.1.3. To maintain the stability of the part quality in the regular mass production.

3.2. Scope

This activity shall apply to parts that require checking gauge and checking fixtures that was advised by PCSB [QE/QRE](#) or R&D Department only.

3.3. Vendor Responsibility

Based on Location Concept Drawing (LCD), vendors shall prepare checking fixtures and checking Gauge to achieve the accuracy level of parts. The checking Fixtures and Checking Gauge (CG) shall be able to show all dimensional items, surface location and measuring points can meet the Part Inspection Standard (PIS) requirements.

- 3.3.1. Upon receiving checking fixture specification from PCSB [QE/QRE](#), vendors shall study the location concept drawing, part drawing and CAD data (if available) to prepare a Checking Fixtures (CF) and Checking Gauge (CG) drawing.
- 3.3.2. This CF and CG drawing shall be submitted to PCSB [QE/QRE](#) for approval.
- 3.3.3. Vendor shall fabricate the CF and CG according to the approved drawing.
- 3.3.4. After completion, the CF and CG [data](#) shall be submitted to [QE/QRE](#) PCSB for approval.
- 3.3.5. Vendors shall update the Checking Fixture and the Checking Gauge according to the latest Engineering Change Instruction ([if applicable](#))
- 3.3.6. Vendors shall follow the instructions from the Parts Matching Team regarding CF specifications and CF Check-sheets. Detail activities that related with Parts Matching shall be arranged by the Parts Matching Team.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 14 of 45

3.3.7. Based on report from PCSB [QE/QRE](#), vendor shall make improvement if necessary.

3.3.8. Maintenance and the accuracy of the Checking Fixture shall be Vendor's responsibility. Vendors shall maintain the function of the Checking Fixture and the Gauge. [Vendor shall establish Checking Fixture manual for these purposes.](#)

4. PART ACCURACY SHEET (PAS)

4.1. Purpose

Part Accuracy sheet (PAS) is used to ensure that all parts supply complies with quality requirement standard.

4.2. Scope

Parts accuracy sheet applies only for part supplied to PCSB that requires checking fixture only.

4.3. Vendors Responsibility

4.3.1. Vendors shall prepare the Part Accuracy Sheet (PAS) (Attachment 4) after receiving preparation drawing or checking fixture (CF) spec. The PAS should be completed at least 2 month before the vendor pilot production. (Please see the attached PAS form).

4.3.2. Vendors shall submit the original PAS to PCSB [QE/QRE](#) department for approval.

4.3.3. [QE/QRE](#) PCSB shall request vendors to amend the PAS form if deem fit and vendor shall resubmit again after the amendment has been made.

4.3.4. Once the PAS is approved, vendors shall keep the control copy. Master copy shall be kept by [QE/QRE](#) department.

4.3.5. Vendors shall maintain and up date PAS as necessary. Up dated PAS shall be submitted to PCSB [QE/QRE](#) for approval.

4.3.6. Any sample with checking fixture submitted for evaluation shall be accompanied with approved PAS data.

 Perusahaan Otomobil Kedua Sdn. Bhd.		VENDOR QUALITY MANUAL	
TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 15 of 45

5. QUALITY CONTROL PROCESS CHART (QCPC)/ CONTROL PLAN

5.1. Purpose

To identify all process and method that shall be control by vendor to ensure the quality in their manufacturing process meet PCSB standard.

5.2. Scope

The vendor shall develop QCPC at the system, subsystem, component and or material level for product supplied, including those for processes producing bulk materials as well as parts.

The QCPC shall indicate the process flow-chart, control point, standards, inspection frequency, inspection equipment, methods, inspector, machines for production and specified reaction plan when the process becomes unstable or not statistically capable. Vendor shall include the use of appropriate statistical tools to monitor special characteristics (∇S , ∇E , ∇R , ∇A) wherever applicable.

5.3. Vendor Responsibility

Vendor shall make QCPC according to the quality standard of each process. The inspection items in the QCPC shall describe detail control by using quality check sheets/ SOP.

- 5.3.1. Vendor shall complete the QCPC draft before T0 sample and submit to PCSB-QE Department (same timing with Part Inspection Standard submission to PCSB)
- 5.3.2. Vendor shall ensure that the processes are feasible. The QCPC shall be up-dated to make sure that what are written in the QCPC is the same with the actual manufacturing process.
- 5.3.3. QCPC shall be reviewed and updated when any changes affecting product, manufacturing processes, measurement or supply sources.
- 5.3.4. In the mass production stage, Vendor has the responsibility to maintain the QCPC of the process.
- 5.3.5. No temporary process is allowed at the start of the mass production. If it is unavoidable, Vendor must inform PCSB-QE Department the details of the process and the timing when that process will be changed.
- 5.3.6. To provide appropriate understanding of the process in the vendor's factory, Vendor shall provide PCSB-QE Department a process layout which shows the relationship of the Quality Assurance checking points



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 16 of 45

of the QCPC to the manufacturing process, tools and gauges. This process layout must also include Receiving Inspection and Automated Inspection built into the machinery.

6. COMPUTER AIDED DESIGN (CAD) DATA AND TECHNICAL INFORMATION REQUEST

6.1. Purpose

To provide guideline for vendor the procedure needed for requesting Computer Aided Design (CAD) data, technical drawing and technical information from Perodua R&D department.

6.2. Scope

This procedure shall cover technical information requested by approved Perodua vendor.

6.3. Vendor Responsibility

- 6.3.1. Vendor shall request CAD data using CAD data communication sheet (Attachment 5) and submit the request to PCSB PVD Department.
- 6.3.2. Upon approval from PVD Department, the communication sheet shall be submitted to PCSB R&D Department for final approval. Upon completion and approval, vendor shall collect CAD data [direct](#) from PCSB R&D department.
- 6.3.3. For technical drawing and technical standard (DTS, TIS etc.) vendor shall make a request through PCSB PVD department. Upon approval, the technical drawing and technical standard shall be forwarded to vendor through PCSB PVD department.

7. ENGINEERING CHANGE REQUEST (ECR) & ENGINEERING CHANGE INSTRUCTION (ECI)

7.1. Purpose

- 7.1.1. To provide guideline for technical changes requested by Vendors related to parts or processes.
- 7.1.2. To inform the Vendor on their responsibility on Engineering Change Instruction (ECI) issued by PCSB.

7.2. Scope

- 7.2.1. Engineering Change Request (ECR) (Attachment 6) shall apply to any changes of the material specifications, the dimension, appearance or other items specified in technical drawing or standards, requested by vendors to PCSB for all parts supplied to PCSB.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 17 of 45

7.2.2. Engineering Change Instruction (ECI) (Attachment 7) shall apply to any changes of the material specifications, the dimension, appearance, parts number or other items specified in technical drawing or standards, instructed by PCSB to all vendors for all parts supplied to PCSB.

7.3. Vendor Responsibility

7.3.1. Any technical changes requested to PCSB, vendor shall fill out the Engineering Change Request Form and submit to PCSB-PVD Division.

7.3.2. PCSB-R&D Division shall study and make decision to reject or to accept the Vendor's request. Vendor shall get the ECR reply through PCSB-PVD Division.

7.3.3. When vendor received ECI from PCSB, vendor shall revise the QCPC, the PIS, the Limit Sample, and the Checking Fixture if necessary. The revised documents shall be submitted to PCSB-QE Dept. for approval.

8. PACKING STYLE INFORMATION

8.1. Purpose

To control packaging of vendor parts supply to PCSB to ensure parts not deteriorate or damage as the result of packing style

8.2. Scope

This procedure covers parts supply to Perodua from pilot production stage up to mass production stage.

8.3. Vendor Responsibility

8.3.1. Vendor shall propose the packing style information (Attachment 8) to PCSB logistic Dept at least 1 month before starting of pilot production.

8.3.2. Vendor shall ensure that the packing style information is approved before sending parts for pilot production in PCSB.

8.3.3. Vendor shall resubmit their packing style information when ECI is issued regarding changes in part number or technical changes that affect the packing style.

8.3.4. Any changes required by vendor in packing style during mass production stage shall be approved by PCSB logistic department before supply to PCSB.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 18 of 45

9. IDENTIFICATION OF PRODUCTION DATE

9.1. Purpose

For traceability and control of the specific parts to ensure the safety and function of Perodua vehicle

9.2. Scope

Safety, function parts, big size parts etc. (Specified in part drawing).

9.3. Vendor Responsibility

- 9.3.1. Vendor shall confirm which part that requires identification and confirm the location of the production code before start making tool.
- 9.3.2. Vendor shall inform PCSB-QE on the code use for identification and traceability of the product.
- 9.3.3. Any correction on production code after production shall be inform and approved by PCSB-QE department.
- 9.3.4. No wrong code product shall be delivered to Perodua.
- 9.3.5. Vendor shall control and record the identification of the product.

10. LIMIT SAMPLE

10.1. Purpose

To establish a visual or a sensory characteristic standard as a supplement of the PIS when the quality characteristic is difficult to define and communicate by any other method.

10.2. Scope

The Limit samples shall be use to define the acceptable limits for any quality characteristic that is difficult to define by measuring method.

PCSB should define the acceptable levels of the part quality for the PCSB Incoming Inspection references.

10.3. Vendor Responsibility

- 10.3.1. Limit samples shall be prepared for the items stated “as per limit samples” in the PIS.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 19 of 45

- 10.3.2. Part samples should also be created to define the problems that are discovered in the production preparation stage and the mass production stage.
- 10.3.3. Vendor shall select limit samples that represent their process capability. PCSB-QE or Part Matching Team shall evaluate the quality of the part based on the fitting condition of the completed vehicle.
- 10.3.4. At least two sets of the limit samples shall be submitted to PCSB-QE Dept. for approval. When it is approved, one sample shall be kept by Vendor QC department for reference and other sample can be use in vendor production line for reference.
- 10.3.5. All limit sample use shall be approved and tag properly.
- 10.3.6. Vendor shall update the limit sample when necessary or when requested by PCSB.
- 10.3.7. For Sub-Vendor appearance items, the vendor shall develop limit samples with their Sub-Vendor.

11. PART SAMPLE SUBMISSION TO PCSB

11.1. Purpose

To assure sample parts submitted to PCSB are identified clearly.

11.2. Scope

This procedure shall apply to all part samples submitted to PCSB.

11.3. Vendor Responsibility

- 11.3.1. All sample parts shall be submitted with PIS data and SPC data where applicable.
- 11.3.2. Sample Part Tag (Attachment 9) shall be placed on every pallet/ containers delivered to PCSB.
- 11.3.3. Vendor shall identify the production date on all containers, packaging or parts (applicable for big parts only).
- 11.3.4. Vendor shall indicate the die number or the cavity number on the part if there are more than one dies to make the part.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 20 of 45

11.4. Evaluation Procedure

11.4.1. Vendors shall first evaluate the sample part following Part Inspection Standard (PIS) and fill Part Inspection Standard data and submit the sample to PCSB R&D and QE Department.

11.4.2. PCSB shall then evaluate the sample and make a judgment. If the part failed, vendor shall take countermeasures and re-submit the parts to PCSB.

11.4.3. PCSB shall re-evaluate and re-judge the improved parts.

12. MASTER SAMPLE

12.1. Purpose

To assist in defining the production standard of the part produced and to maintain the traceability of the parts quality and tooling process.

12.2. Scope

All parts are involved in this practice.

12.3. Vendor Responsibility

12.3.1. Vendor shall generate master sample for all parts produce for PCSB.

12.3.2. Vendor shall make master sample that comply with all 100% requirement stated in parts drawing.

12.3.3. Vendor shall produce full 100% dimensional report and other technical report stated in the parts drawing.

12.3.4. All master samples shall be approved by PCSB QA department.

12.3.5. Vendor shall store the master sample in a manner that preserves the original “approved” condition.

12.3.6. All master samples shall be clearly identify and [kept at least 3 years after the affected part phased out.](#)

Note

If PCSB requests the Vendor to confirm the master sample, Vendor shall use this master sample for verification.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 21 of 45

13. INITIAL STAGE CONTROL (DESIGN/PROCESS CHANGE)

13.1. Purpose

To identify and control, the changes in the Vendor's manufacturing process and assure the quality of the first goods and smooth start up.

13.2. Scope

The control shall cover all first delivered parts supplied for production line at PCSB.

13.3. Vendor Responsibility

13.3.1. Initial Stage Control Information (Vendor) (Attachment 10) shall be submitted to PCSB-QE Department at least 3 months before implementing the change.

13.3.2. The request shall be approved by PCSB before implementing the change. If requested, vendors shall attain the additional information requested by PCSB (i.e. sample, survey etc.)

13.3.3. If approved, vendors shall put proper identification of first goods when supplying parts to PCSB with related inspection data (refer item 14)

13.3.4. Vendors shall conduct appropriate evaluation of first goods before supply to PCSB.

14. INDICATION OF FIRST DELIVERED PARTS

14.1. Purpose

To evaluate the first batch product received by PCSB from the Vendor at production preparation or mass production using the regular/ permanent process material, tool and machine.

14.2. Scope

This procedure shall apply to first batch of the regular process parts that are submitted to PCSB during the production preparation stage or mass production stage.

14.3. Vendor Responsibility

14.3.1. Parts submitted to Perodua for evaluation shall be from regular process tool using the regular material and process.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 22 of 45

14.3.2. Vendor shall submit the test report using Parts Inspection Standard (PIS) and Parts Accuracy Sheet (PAS where applicable) together with the first lot of the parts delivered to PCSB.

14.3.3. Vendor shall attached First Delivered Parts Information (Attachment 11) in each of the first five containers from the first lot delivered, and Design/Process Change Label (Attachment 12) displayed outside the first five containers delivered to PCSB.

14.3.4. Parts shall be use at production line upon approval from PCSB [QE](#) dept.

15. MASS PRODUCTION INSPECTION BY VENDOR

15.1. Purpose

To maintain the quality of parts shipped to PCSB in Mass Production Stage. Vendor must perform inspection in the production process line and Final Inspection before packing.

15.2. Scope

All local parts that are supplied to PCSB shall be inspected by Vendor before shipping.

15.3. Vendor Responsibility

15.3.1. Vendor shall control the process based on the QCPC and inspect the part according to the Part Inspection Standard during the production process.

15.3.2. If requested by PCSB, Vendor shall submit the sampling data of the quality inspection to PCSB-[QP](#) every month following the specified items in the Part Inspection Standard (PIS).

15.3.3. All part shall be shipped or delivered to PCSB following production lot order.

15.3.4. Vendor shall assure the quality of the parts or material supplied by their sub-vendor by performing incoming inspection in the vendor's factory.

16. MASS PRODUCTION INCOMING INSPECTION BY PCSB

16.1. Purpose

To prevent defective parts delivered to the Production line in PCSB's Factory.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 23 of 45

16.2. Scope

All parts that are delivered to PCSB shall be verified by PCSB-QP Department.

16.3. Vendor Responsibility

16.3.1. Mass production parts delivered to PCSB shall be verified by PCSB-QC Department using the Part Inspection Standard (PIS). If any problem found during incoming inspection, PCSB-QC department shall inform the vendor immediately.

16.3.2. The Vendor shall do sorting of parts and report in Sorting Check Sheet (Attachment 13).

16.3.3. Vendors shall not deliver the parts in their or third party inventory until sorting of defective parts is completed.

16.3.4. PCSB-QC department shall issue Quality Problem Countermeasure Report (QPCR) if necessary.

16.3.5. According to the investigation result the vendor shall make the plan schedule, for the countermeasures to be implemented.

16.3.6. Vendor shall reply to PCSB within 2 days a temporary countermeasure plan in writing by fax.

16.4. Defective report

The defective parts will be rejected and returned to the vendor by PCSB-Production Control Department. After receiving the parts with Defective parts ticket or problem sheet, Vendor must analyze the cause of problem and replace those parts as soon as possible.

17. QUALITY PROBLEM COUNTERMEASURE REPORT (QPCR)

17.1. Purpose

To inform the vendor on the quality problem encountered and countermeasures needed from the vendor to prevent reoccurrence of the problem at PCSB.

17.2. Scope

The parts non-conformance detected in production trials and mass production are communicated formally using problem report sheet i.e. Quality Problem Countermeasure Report (QPCR) – Attachment 14



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 24 of 45

17.3. Vendor Responsibility

- 17.3.1. If problems encountered PCSB QC shall issue the problem sheet to the vendor describing the problem. PCSB and the vendor shall work together and take appropriate counter measures immediately to prevent reoccurrence of the problem before the next trial or the next delivery.
- 17.3.2. As soon as the Vendor has been notified by PCSB about non-conforming parts, the vendor shall take immediate temporary corrective action (i.e. sorting or rework) of the parts.
- 17.3.3. PCSB shall issue the QPCR for the following condition:
- a) Problem related to safety item and or
 - b) Downtime occurs at PCSB and or
 - c) Defect affected monthly pass rate more than 10 %.
- 17.3.4. The Vendor shall reply the QPCR within 10 working days after received.
- 17.3.5. PCSB-QC department shall monitor for 5 consecutive days after the countermeasures being implemented to ensure the effectiveness of the countermeasures.
- 17.3.6. The Vendor shall do sorting or monitor the parts at PCSB when requested.

18. REWORK PRODUCT

18.1. Purpose

- 18.1.1. To specify the control of rework product to ensure full compliance to Perodua requirement.
- 18.1.2. To ensure smooth supply of parts to PCSB production line and to avoid any unnecessary disruption to PCSB production operation.

18.2. Scope

This activity covers the parts supplied to PCSB after mass production stage.

18.3. Vendor Responsibility

- 18.3.1. Upon receiving information regarding quality problem of parts supplied to Perodua, vendor shall response immediately by sorting, segregation or rework of the effected parts.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 25 of 45

18.3.2. If rework, salvage or sorting is necessary, all process of rework operation shall be supported by written procedures or instruction to vendor's workers to ensure compliance to specification.

18.3.3. Vendor shall report the result of sorting, segregation and re-inspection in Sorting Check Sheet (Attachment 13).

18.3.4. Any rework processes must be supported by written procedures and instructions to ensure compliance to specification.

18.3.5. Special identification and segregation of reworked products may be required on shipping container to Perodua.

19. TEMPORARY ADOPTION

19.1. Purpose

To specify the procedures of temporary adoption of supplied product which deviate from specification for the purpose of smooth production operation of PCSB.

19.2. Scope

This activity applies to supply product by vendor which deviate from the specification but to be use in PCSB production line.

19.3. Definition

Deviated product is product which deviates from the specification in any of the following manner.

- a) Nonconforming to drawing, standards etc,
- b) Nonconforming caused by imperfection of material, die, jig, tools etc.
- c) Nonconforming caused by imperfection of drawing, standard etc.

Temporary is a terminology used to authorize the use of product deviating for the specification for a limited quantity and a limited time period. The specification deviating product can be adopted as it is or after additional work or treatment provided the function, safety, merchandise value, interchangeability and reliability of product is maintained as the original product.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 26 of 45

19.4. Vendor Responsibility

- 19.4.1. Before filling temporary adoption application vendor shall conduct meeting with the respective department in PCSB to inform their reason for application.
- 19.4.2. Upon agreement in the meeting, the vendor shall propose the quantity and time period to supply the temporary adoption part.
- 19.4.3. Vendor shall submit the Temporary Adoption Form (Attachment 15) to PCSB-PVD department for initial approval.
- 19.4.4. If accepted, PCSB-PVD Department shall forward the application to PCSB-QC Department for final approval. Temporary adoption for the same deviation of specification from the same vendor shall be limited to once.
- 19.4.5. PCSB-PVD Department shall notify the vendor on the decision after receiving the final decision from PCSB QC Department.
- 19.4.6. Vendor shall make special permanent marking on every temporary adopted part that being deliver to PCSB. The Vendor shall put special tagging on pallets to identify the temporary adopted parts.
- 19.4.7. Vendor shall up date on daily basis respective department in PCSB on the quantity being delivered against the approved quantity in the temporary adoption application.
- 19.4.8. Vendor shall be hold responsible for any claim regarding product liability of the temporary adopted parts.

20. RECORDS AND RETENTION PERIOD

20.1. Purpose

To specify the procedures and retention time for the quality records related to Perodua product.

20.2. Scope

This procedures shall apply to all quality records and documentation related to production of product or parts supply to PCSB.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 27 of 45

20.3. Vendor Responsibility

- 20.3.1. Vendor shall establish and maintain documented procedures for identification, collection, indexing, access, filling, storage, maintenance and disposition (disposal) of quality records.
- 20.3.2. Quality records shall be maintained to demonstrate conformance to specified requirements and the effective operation of the quality system.
- 20.3.3. All quality records shall be legible and shall be stored and retained in such a way that they are readily retrievable in facilities that provide a suitable environment to prevent damage or deterioration and prevent loss.
- 20.3.4. Production parts approval, tooling records, purchase orders and amendments shall be maintained for the length of time that part (or family of parts) is active for production and six calendar years after last product supplied to PCSB.
- 20.3.5. Quality performance records (e.g. PIS, control charts, test results) shall be retained for eight calendar years in which they were created.
- 20.3.6. Records of internal quality system audits and management review shall be retained for three years.

21. QUALITY ASSURANCE FOR SUB-VENDOR

21.1. Purpose

To establish PCSB's requirements on Vendor's responsibility to maintain and control quality assurance activities in their Sub – vendor

21.2. Scope

All Sub-Vendors related with the raw materials and the components that are used by the vendor shall be controlled by the vendor.

21.3. Vendor Responsibility

- 21.3.1. The Vendor shall assure that the quality of the part and/or material that are supplied to the vendor shall be inspected by the sub-vendor.



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 28 of 45

21.3.2. Vendors shall develop each sub-vendor to implement PCSB-VQM, to keep the quality control process chart implementation. Vendor shall set up the documentation, built in quality, in process and related facilities and practices in the sub-vendor.

21.3.3. Vendor shall ensure that the sub-vendor implements the same/ similar activities following this manual to assure quality at each stage by using this PCSB-VQM.

SECTION C: OTHERS

1. SAFETY ATTIRES

All vendors' personnel are required to wear [appropriate safety apparel when entering Perodua plant.](#)

SECTION D: ATTACHMENTS

Notes: Formats attached in this manual are for reference only. Any changes to the format will be notified by related person in charge from time to time



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 29 of 45

1. Attachment 1: Vendor Representative Information Form

TO: **PERODUA AUTO CORPORATION SDN BHD**
Procurement and Vendor Department

VENDOR REPRESENTATIVES INFORMATION

VENDOR :	ADDRESS :	DATE :
----------	-----------	--------

FUNCTION	NAME	DESIGNATION	DEPARTMENT	PHONE / FAX	H/PHONE
MAIN CONTACT REPRESENTATIVES WITH PERODUA					
QUALITY CONTROL/ QUALITY ASSURANCE					
PRODUCTION PREPARATION					
NIGHT SHIFT					

Note:
Any changes of representative shall be informed to Perodua within 10 days.

APPROVED BY

(Vendor Top Management)

VQM001-A



Perusahaan Otomobil Kedua Sdn. Bhd.

VENDOR QUALITY MANUAL

TITLE
Vendor Quality Manual

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
Quality Assurance Department &
PVD Department

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
30 of 45

2. Attachment 2: Production Preparation Plan

PARTS PRODUCTION PREPARATION PLAN												
Part Number	Part Name :	Model	Organisation :	REVISION HISTORY								
				Rev	Rev Content	Date	PIC					
REASON FOR SUBMISSION ☐ New parts (new model) development ☐ Parts localization ☐ New method. ☐ Engineering changes (ECI) ☐ Tooling : Transfer, Replacement, Refurbishment or Additional ☐ Others :				Address : Prepared by : Checked by : Approved by :								
PRODUCT OUT LINE (Pls provide rough sketch)		PRODUCTION PREPARATION PLAN										
		NO	ITEM	DIV	MONTH / YEAR							
			PERODUA MASTER SCHEDULE									
			Trial									
			1st Pilot Production (1PP)									
			2nd Pilot Production (2PP)									
			Mass Production									
			8PTT Visit									
		1	Receive DRW, RDP, Prod DRW									
		2	Production Preparation Plan.									
			2.1 Process Planning									
			2.2 Tooling / Facility design									
			2.3 Tooling procurement (until tuning).									
			2.4 Die / Jig proc (until tuning)									
			- Trial before installation.									
			- Pre check before installation.									
			- Check jig accuracy									
			- Installation									
			- Final tuning									
			- Inspection/audit									
			2.5 Prepare Cif									
		3	Production Trial.									
			3.1 Line trial									
			3.2 1st PP									
			3.3 2nd PP									
			3.4 Sample submission									
			3.5 Worker training									
			3.6 Supplier kick off meeting									
		4	Standards									
			4.1 Parts Inspection Standard (PIS)									
			4.2 QC Process Chart.									
			4.3 Standard operation procedure (SOP)									
		5	Manufacturing Quality Check.									
			5.1 First article inspection.									
			5.2 Reliability test.									
			5.3 Initial variation control.									
		6	Engineering Change.									
			6.1 Major ECI.									
			6.2 Minor ECI									
		7	Colour / Grain approval									
		8	Limit sample									
MANUFACTURING PROCESS FLOW												
PRODUCTION CAPACITY (MONTHLY)												
		LEGEND : Plan Actual										
		FOR PERODUA USE ONLY										
		☐ Approved ☐ Rejected ☐ Others :										
		Comment :				Approved by :		Name / Designation				
PROGRESS IN PRODUCTION TOOLING / PROCESS												
Production tooling (Finish)		Production process (Finish)		Progress (A: prod tooling/process, B: Prod tooling /tentatiff process, c: Prototype tooling					Reason of provisional countermeasures		Provisional countermeasures (Description)	
Planned Actual		Planned Actual		SB LPVV 1PP 2PP Mass Pro Try								
Original												

VQM002-A





VENDOR QUALITY MANUAL

TITLE
Vendor Quality Manual

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
**Quality Assurance Department &
PVD Department**

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
31 of 45

3. Attachment 3: Part Inspection Standard (PIS)

[illegible]

TITLE	Vendor Quality Manual
-------	------------------------------

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
**Quality Assurance Department &
PVD Department**

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
32 of 45

Part Inspection Standard (PIS) Continues...

[illegible]



Perusahaan Otomobil Kedua Sdn. Bhd.

VENDOR QUALITY MANUAL

TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 33 of 45

Part Inspection Standard (PIS) Continues...

Part Number:	Rev:	PART INSPECTION STANDARD	Page (/)
PART SKETCH			

OE-19-C



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1 st JUNE 2005	EFFECTIVE DATE 1 st JUNE 2005	PAGE NO 34 of 45

4. Attachment 4: Part Accuracy Sheet (PAS)

 PART ACCURACY SHEET									
☐ Sample T. ☐ GPM / PM ☐ Trial ☐ Pilot Prod. ☐ Mass Prod. Page (/)									
PERODUA MANUFACTURING (QA DEPT.)						Measuremet Date : / /			
PART NAME						JIG NO			
PART NO.						MODEL			
VENDOR						☐ RH ☐ LH ☐ SINGLE PART			
APPROVAL									
PERODUA (QA DEPT.)					VENDOR				
Approved by	Checked by	Checked by	Approved by	Checked by	Prepared by				
PAS Accuracy Points OK X 100% Total Points _____ X 100% =	Rev	Date	Content			Vendor		PERODUA	
						Checked	Approved	Checked	Approved

Route : Vendor ↔ Perodua(QA) ↔ Copy(Related Section) QE-05-B



Perusahaan Otomobil Kedua Sdn. Bhd.

VENDOR QUALITY MANUAL

TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1 st JUNE 2005	EFFECTIVE DATE 1 st JUNE 2005	PAGE NO 35 of 45

5. Attachment 5: CAD Data Communication Sheet

PERODUA TECHNICAL ADMINISTRATION DEPARTMENT										ON-LINE DATA TRANSFER Tel : 603-6733 8888 ext. 3679 / 5547 e-Parcel: CADMIN@PERODUA.COM.MY Fax: 603-6733 0343									
STATUS ☐ W.I.P ☐ RELEASED		MODEL		CAD DATA COMMUNICATION SHEET				REQUESTER TEL: _____ DATE: _____		PVD TEL: _____ DATE: _____		DEPT. IN CHARGE TEL: _____ DATE: _____		Page /					
COMPANY INFORMATION				CAD/CAM SYSTEM				Fax: _____						ENG. IT SECTION					
NAME: _____				☐ CATIA V(4. . ☐ CATIA V(5. .)				Approved		Checked		Prepared		Approved					
DEPT.: _____				☐ CAELUM II(☐ PRO/E ()															
PIC.: _____				☐ I-DEAS (☐ UNIGRAPHICS (															
TEL: _____				☐ OTHERS (															
PERODUA SYSTEM ☐ CATIA V(4.2.2) ☐ CAELUM II V(3.17)		PURPOSE ☐ PRODUCTION ☐ PROTOTYP ☐ LOCALIZATION		TOOL DESIGN ☐ TOOL PRODUCTION ☐ REFERENCE		RELEASE TIMING ☐ BEFORE DWG REL ☐ DWG RELEASE ☐ AFTER DWG REL		PROVIDED MEDIA ☐ CD-R/RW ☐ e-Parcel ☐ DISKETTE ☐ 4mm DAT (DDS 1,2,3 & 4)		FORMAT NATIVE FORMAT: ☐ CATIA v4 ☐ CAELUM-W/F COMPRESSION: ☐ TAR ☐ Z CONVERSION: ☐ CAT-EXP ☐ IGES ☐ ZIP(WINDOWS)									
NO	PART NUMBER	PART NAME				DATABASE				NOTE		FILE NO.							
1																			
2																			
3																			
4																			
5																			
6																			
7																			
8																			
9																			
10																			
REMARKS		ACKNOWLEDGEMENT (RECEIVED)				MEDIA NO. OR ON-LINE NO.				RELEASE NO.									
		SIGNATURE & DATE																	
		NAME																	
		COMPANY																	
TARGET DATE		MTH		DAY		DEPARTMENT													
TECHNICAL ADMINISTRATION DEPARTMENT ENG. INFORMATION SECTION, R&D, PERODUA ☐ SUPPLIER --> PVD --> DPT. IN CHARGE --> R&D-TA --> SUPPLIER ☐ REG. DPT. --> R&D-TA --> SUPPLIER (Minor change / ECI matter) ☐ REG. DPT. --> R&D-TA --> REG. DEPT. (Inter-department. i.e. QA, PE, etc.)																			

R3.030D





Perusahaan Otomobil Kedua Sdn. Bhd.

VENDOR QUALITY MANUAL

TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1st JUNE 2005	EFFECTIVE DATE 1st JUNE 2005	PAGE NO 36 of 45

6. Attachment 6: Engineering Change Request (ECR)

TO : _____		DAIHATSU MOTOR CO. LTD	
THROUGH : PERODUA MANUFACTURING SDN. BHD. (95999T)			
ENGINEERING CHANGE REQUEST SHEET		PMSB'S NO.	
		PROPOSER'S NO. (Optional)	
PART NO.	PART NAME	MODEL	
REASON FOR REQUEST COMMENTS: CHECK APPLICABLE REASON (S) Y PERFORMANCE IMPROVEMENT Y SUPPLIER PRODUCTIVITY IMPROVEMENT Y PERODUA MANUFACTURING PRODUCTIVITY IMPROVEMENT Y COST REDUCTION Y OTHERS (Describe)		ESTIMATED PRICE CHANGE ± / Piece	
		ESTIMATED MASS CHANGE ± g / Piece	
CONTENTS OF REQUEST WITH COMPARATIVE OF THE PORTION CONCERNED (Please use additional page for providing detailed drawing and / or explanation)			
THIS PROPOSAL HAS BEEN DISCUSSED WITH PERODUA MANUFACTURING SDN. BHD. (Name & Dept. if yes):			
THIS PROPOSAL HAS BEEN DISCUSSED WITH DMC (Name & Dept. if yes):			
COMPANY'S NAME:	SIGNATURE(S)		
DATE AUTHORIZED:	NAME IN TYPE		
PERODUA'S MANUFACTURING COMMENTS			
Y RECOMMEND DMC TO ACCEPT			
Y CANNOT ACCEPT			

COMPANY'S NAME:	SIGNATURE (S)		
PERODUA MANUFACTURING SDN. BHD.			
DATE AUTHORIZED:	NAME IN TYPE		
TO: _____		Y INTERIM REPLY	
DMC'S REPLY		FINAL REPLY DISPATCHED BY:	
Y WE ACCEPT YOUR REQUEST (ECI NO. _____)			
Y WE CANNOT ACCEPT YOUR REQUEST			
IMPLEMENTATION CONDITION OR REASON			
		APPROVED	CHECKED
			PREPARED
STAFF CODE:		STAFF NAME:	
APPROVED	/ /	CHECKED	/ /

TITLE	Vendor Quality Manual
-------	------------------------------

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
**Quality Assurance Department &
PVD Department**

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
37 of 45

7. Attachment 7: Engineering Change Instruction (ECI)

[illegible]



Perusahaan Otomobil Kedua Sdn. Bhd.

VENDOR QUALITY MANUAL

TITLE
Vendor Quality Manual

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
Quality Assurance Department &
PVD Department

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
38 of 45

8. Attachment 8: Packing Style Information

PERODUA MANUFACTURING SDN BHD (959997) Perodua Automotive Centre Sungai Choh Locked Bag 226 48009 Rawang Selangor		Telephone Number : 03-6092 8888 03-6733 8888 Facsimile Number : 03-6733 0509 03-6090 2109										
PACKING STYLE INFORMATION												
INSTRUCTIONS (PLEASE READ) 1 Please refer to manual for Packing Style Information. 2 Please cross (X) in relevant column. 3 No handwritten form is acceptable. 4 Polybox size must follow the indicated size only (Toyota Poly Box) 5 Please attach picture for a) Single part (1 piece) b) Condition part in packing - actual & not sample packing												
(To be filled by vendor) VENDOR : _____ E-MAIL ADDRESS : _____ DATE : _____ PREPARED BY (NAME / PIC) : _____ DEPT. : _____ SIGNATURE : _____												
DETAIL INFORMATION												
A PART	PART NAME : _____ PART NO : - - SHOP : ☐ BODY ☐ CMK ☐ ASSEMBLY ☐ PAINT ☐ OTHERS - PLEASE SPECIFY : _____ MODEL : <table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="text-align: center;">☐ KANCIL</td> <td style="text-align: center;">☐ KELISA</td> <td style="text-align: center;">☐ D73A</td> </tr> <tr> <td style="text-align: center;">☐ KEMBARA</td> <td style="text-align: center;">☐ RUSA</td> <td style="text-align: center;">☐ OTHERS</td> </tr> <tr> <td style="text-align: center;">☐ KENARI</td> <td style="text-align: center;">☐ 002L</td> <td style="text-align: center;">Please specify Project Code</td> </tr> </table>			☐ KANCIL	☐ KELISA	☐ D73A	☐ KEMBARA	☐ RUSA	☐ OTHERS	☐ KENARI	☐ 002L	Please specify Project Code
	☐ KANCIL	☐ KELISA	☐ D73A									
☐ KEMBARA	☐ RUSA	☐ OTHERS										
☐ KENARI	☐ 002L	Please specify Project Code										
PART SPECIFICATION a) Color : _____ b) Weight : _____ gram c) Qty/car : _____ pc(s) BACK NO : (To be decided by Logistics)												
B PACKING STYLE / CONTAINER	TYPE OF CONTAINER (PLEASE CHOOSE ONLY ONE) i) Toyota Poly Box (TP) : (L x W x H) mm + Weight (gram) - <i>corrugated & carton box not encouraged</i> <table style="width: 100%;"> <tr> <td>☐ TP 131 ~ 335 x 168 x 103 (345)</td> <td>☐ TP 341 B ~ 503 x 335 x 103 (1015)</td> <td>☐ TP 482 L ~ 838 x 503 x 195 (2000)</td> </tr> <tr> <td>☐ TP 331 ~ 335 x 335 x 103 (630)</td> <td>☐ TP 342 ~ 503 x 335 x 195 (1360)</td> <td>☐ TP 484 L ~ 838 x 503 x 380 (3100)</td> </tr> <tr> <td>☐ TP 332 ~ 335 x 335 x 195 (870)</td> <td>☐ TP 362 ~ 670 x 335 x 195 (1800)</td> <td>☐ TP 392 ~ 1005 x 335 x 195 (2500)</td> </tr> </table> ☐ Others - Please specify : _____ (case to case basis) ii) ☐ Racking - Please specify (mm) : L _____ W _____ H _____ (Recommended with wheel, hook & stopper - P2 to provide specification)			☐ TP 131 ~ 335 x 168 x 103 (345)	☐ TP 341 B ~ 503 x 335 x 103 (1015)	☐ TP 482 L ~ 838 x 503 x 195 (2000)	☐ TP 331 ~ 335 x 335 x 103 (630)	☐ TP 342 ~ 503 x 335 x 195 (1360)	☐ TP 484 L ~ 838 x 503 x 380 (3100)	☐ TP 332 ~ 335 x 335 x 195 (870)	☐ TP 362 ~ 670 x 335 x 195 (1800)	☐ TP 392 ~ 1005 x 335 x 195 (2500)
	☐ TP 131 ~ 335 x 168 x 103 (345)	☐ TP 341 B ~ 503 x 335 x 103 (1015)	☐ TP 482 L ~ 838 x 503 x 195 (2000)									
☐ TP 331 ~ 335 x 335 x 103 (630)	☐ TP 342 ~ 503 x 335 x 195 (1360)	☐ TP 484 L ~ 838 x 503 x 380 (3100)										
☐ TP 332 ~ 335 x 335 x 195 (870)	☐ TP 362 ~ 670 x 335 x 195 (1800)	☐ TP 392 ~ 1005 x 335 x 195 (2500)										
CONTAINER SPECIFICATION i) Weight of Container : a) Empty _____ gram b) Full _____ gram ii) Quantity / Container : ☐ 2pcs ☐ 5pcs ☐ 10pcs ☐ 20pcs ☐ Others - Please specify : _____ (Kanban Quantity) iii) Color of Container : ☐ Blue ☐ Green ☐ Grey ☐ Black ☐ Others - Please specify : _____ (RED poly box is PROHIBITED) iv) Label Dimension (L x W) mm : Compulsory ☐ A4 (210 x 297) Racking ☐ TP Label (200 x 75) Optional ☐ OTHERS - Please specify : _____ (case to case basis)												
(To be filled by PERODUA) PREPARED BY : _____ DATE : STATUS : ☐ APPROVE ☐ REJECT : REASON _____												
Disclaimer Notwithstanding that the packing style has been approved by PERODUA, the vendor shall at its own costs comply with all instructions issued by PERODUA from time to time for the purpose of improving the said packing style, which may include to cease using the approved packing style and to use a new packing style.			QP7 - 4000 - 004 REVISION : 08 DATED : 18-Aug-04									





TITLE
Vendor Quality Manual

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
Quality Assurance Department &
PVD Department

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
39 of 45

9. Attachment 9: Sample Part Tag

SAMPLE PART TAG

Company Name:

Part number:

Part Name:

Delivery date:

Quantity of delivery:

Batch no / Lot no:

Sample purpose:

Model / Code:

**INSPECTION RESULT OF SAMPLE PARTS
(TO BE FILL BY PERODUA)**

Judgment & comment

OK / NG

Signature / Cop

(Size: 10cm X 21cm) ~ white color

TITLE	Vendor Quality Manual
-------	------------------------------

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
**Quality Assurance Department &
PVD Department**

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
40 of 45

10. Attachment 10: Initial Stage Control Information

[illegible]



TITLE
Vendor Quality Manual

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
Quality Assurance Department &
PVD Department

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
41 of 45

11. Attachment 11: First Delivered Parts Information (Vendor)

**FIRST DELIVERED PARTS INFORMATION
(VENDOR)**

Company Name:
Part No:
Part Name:
Delivery Date:
Quantity of delivery:
ECI No/Process Change No:
Production Stage (e.g. PP/MASS PRO):
Model Code:
Content of change:

THIS SECTION TO BE FILLED BY PERODUA

Assemble Date:
Chassis no/Engine no:
INSPECTION RESULT
<u>Logistic</u> Judgement and comment OK/ NG
Name & Signature:
<u>Quality Parts</u> Judgement and comment OK/ NG
Name & Signature:
<u>Inspection</u> Judgement and comment OK/ NG
Name & Signature:

(Size: 10cm X 21cm) ~ red color



TITLE
Vendor Quality Manual

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
Quality Assurance Department &
PVD Department

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
42 of 45

12. Attachment 12: Design/ Process Change Label)

 DESIGN/ PROCESS CHANGE LABEL	REF NO:		PART NAME:		REVISION CONTENT:	
	MODEL/ VARIANT/ SHOP		PART NO:		LOT NO:	



Perusahaan Otomobil Kedua Sdn. Bhd.

VENDOR QUALITY MANUAL

TITLE
Vendor Quality Manual

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
Quality Assurance Department &
PVD Department

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
43 of 45

13. Attachment 13: Sorting Check sheet



SORTING CHECK SHEET

DATE : _____

P.I.C	NAME	PHONE & FAX NO.
VENDOR		
QA PERODUA		03-60928888 - 5448

DETAILS INFORMATION

NO	PART NAME	PART NUMBER	MODEL	ASSY		BODY		LOGISTIK	
				OK	NG	OK	NG	OK	NG
1									
2									
3									
4									
5									
6									
7									
8									

ACTION / COMMENT

VQM003-A



TITLE	Vendor Quality Manual
-------	------------------------------

DOCUMENT NO
VM4-2000-001

REV. NO
0

ISSUED BY
**Quality Assurance Department &
PVD Department**

DATE ORIGINAL ISSUE
1st JUNE 2005

EFFECTIVE DATE
1st JUNE 2005

PAGE NO
44 of 45

14. Attachment 14: Quality Problem Countermeasure Report (QPCR)

	TO : _____	REF NO : _____	ISSUING DEPT : _____
	DEPT : _____	DATE OF ISSUE : _____	

QUALITY PROBLEM COUNTERMEASURE REQUEST (QPCR)

Model :	Stage	Rank	Manager	Engineer	Svisor
Chasis No :	Pilot ☐ Mass Prod. ☐	S General ☐			
E/g No./Unit No :	Time of Occurance Morning ☐ Afternoon ☐ Night ☐	Place of Occurance	Defective Item		
Part No :			Appearance ☐		
Part Name :			Dimension ☐		
			Function ☐		
			Others : _____		

Details of Defect :	Sketch
QA Dept Comment	
	Defective Part / Unit / Vehicle Disposal 1. Separation Work Operation [Repair] Result : NG Repair : 2. Return : Date :
Required date of answer :	[only for S]

TO : _____	REPLY DATE : _____
COUNTERMEASURE	

Defect Item Disposal (Including Stock/in line)	Manager	Engineer	Svisor
	S		
Cause of Defect	Sketch		
Details of Defect			
Details of Countermeasure			

Implementation	Date :	Lot No :	Chassis No :	E/g No :
Result of Checking	OK ☐ NG ☐	Comment : _____	_____	_____
				[only for S] ☐



TITLE Vendor Quality Manual		DOCUMENT NO VM4-2000-001	REV. NO 0
ISSUED BY Quality Assurance Department & PVD Department	DATE ORIGINAL ISSUE 1 st JUNE 2005	EFFECTIVE DATE 1 st JUNE 2005	PAGE NO 45 of 45

15. Attachment 15: Temporary Adoption

Quality Assurance Dept Perusahaan Otomobil Kedua Sdn Bhd		TEMPORARY ADOPTION APPLICATION			
To: ☐ Quality Inspection ☐ Quality Incoming & Parts ☐ Quality Audit ☐ Quality PDI Others (please specified): _____		Distribution: ☐ QA General Manager ☐ QC General Manager ☐ Production 1 General Manager ☐ Production 2 General Manager Others (please specified): _____			
From: _____		Date of Issue: _____			
Section A (to be filled by requestor)					
Part No: _____		Part Name: _____ Model: _____			
Content of Defect:		Illustration/sketch:			
Cause/Suspected Cause:					
Action Taken:					
Permanent Countermeasure:					
Details of Request:					
Temporary Adopted Product Identification:		Approved	Checked	Prepared	
Chassis No. _____	Engine No. _____	Lot No. _____	Manager/ A. Mgr	Engineer	Exec/ Supervisor
Section B (to be filled by QA dept)					
Kind of Temporary Adoption ☐ Used as it is ☐ Used after special additional work		Content of Additional Work			
Quantity _____		Unit Price _____			
Result of Investigation/Test		Loss if Scrapped			
Condition for Adoption/Reason for Non Adoption		Acknowledge by PVD (for Out Plant Cases)			
Opinion of Related Section/Department		Judgement ☐ Adopted ☐ Not Adopted			
		QA Department ☐ Approved ☐ Checked			
		☐ Manager ☐ Engineer			
Route: 1. Outplant case: Requestor → PVD → Quality Parts → PVD → Requestor 2. Inplant case: Requestor → Quality Inspection → Requestor					

QS 8.2.4-B