

**SYNTHETIC TRAINING RECORD — FICTIONAL PARTIES, PEOPLE,
PLACES, IDENTIFIERS, AND EVENTS — NOT A REAL FILING**

Shipment Logger and Chain-of-Custody Exhibit

Admitted October 7, 2025

United States District Court for the Western District of North Carolina Blue Ember Biologics, LLC v. Granite Heron Logistics, Inc. Civil Action No. SYN-WDNC-24-CV-0520

This exhibit collects the authenticated transport records for shipment GHL-ASH-091224-087 and validation lot BE214-VL-2409A. Granite Heron’s custodian identified the custody form, route entries, refrigeration-controller extract, contact log, and a readable rendering of the preserved CryoTrace source export. The assigned equipment was tractor GH-4821 and trailer TR-7714. Payload monitor CTX9-44721 used Eastern Daylight Time.

Solstice Gate Analytics tendered sealed shippers at 61 Pelham Lab Way in Greenville, South Carolina 29615. The destination was Blue Ember’s frozen receiving area at 1847 Cinder Ridge Parkway in Asheville, North Carolina 28803. Release Specification BE214-RS-03, Revision 3 required continuous carriage from minus eighty through minus sixty degrees Celsius, with a minus-seventy operating setpoint.

Admission establishes authenticity and the recorded values, not chemical consequence, legal causation, or damages. The portable rendering does not replace the underlying export, and the exhibit makes no automated judgment about product suitability.

Signed custody sequence

The origin custodian recorded sealed containers, certificate COC-BE214-091224, monitor serial CTX9-44721, and an in-range handoff. Granite Heron accepted physical custody at 11:20 on September 12, 2024. No exterior breach, incorrect identifier, or warmer starting condition was entered. The driver departed Solstice Gate Analytics at 11:47.

Route records place the vehicle at Granite Heron's controlled facility, 802 Granite Heron Way in Fletcher, North Carolina 28732, at 12:46. The trailer entered bay F-4 at 12:49 for a planned operational stage. The sealed payload stayed inside the trailer. A cable was seated at 12:52, tractor power ended at approximately 12:53, and the records contain no affirmative confirmation that the standby circuit energized the refrigeration unit.

After the response described later in this exhibit, the vehicle left Fletcher at 14:18. Blue Ember received the still-sealed load at 15:26. Its signature acknowledged transfer of physical custody only. Receiving personnel immediately retained the logger information and placed the lot in frozen quarantine. The custody form contains no quality release, waiver of the temperature condition, or agreement that later cooling erased the intervening readings.

Payload-monitor curve

The readable curve derives from the preserved CTX9-44721 sampling sequence without interpolation across missing observations. It shows the payload rising above the minus-sixty upper boundary at 13:08. Warming continued to a recorded maximum of minus 42.8 degrees Celsius at 13:37. After refrigeration restarted, the curve declined and crossed back within the authorized band at 14:02.

The boundary-to-boundary duration is fifty-four minutes. Later readings are displayed after the return so the recovery shape remains visible, but they are not averaged backward to recast the excursion. The report also retains the minus-eighty lower boundary and minus-seventy operating setpoint for context. No authorized grace period, rolling average, or single-reading exception appears in the shipment instructions.

The source export's device identifier and clock setting match the origin and custody records. The parties stipulated that the plotted time and temperature values may be considered as recorded. They did not stipulate that the graph proves universal inactivity, validation suitability, negligence, foreseeability, or a particular monetary loss. Those questions require the other admitted evidence and the Court's instructions.

Fletcher event correlation

Granite Heron's route, controller, and contact entries align with the payload curve. A telemetry exception was sent at 13:10 to an inactive archive queue rather than the staffed response queue. No dispatcher acknowledged it then. A yard observation at 13:36 found the refrigeration controller dark. The monitor reached its maximum one minute later.

Personnel restarted tractor power and active refrigeration at 13:38. Transport Operations Manager Tess Holloway received notice at 13:41 and reached bay F-4 at about 13:45. The contact log records attempts to reach Dr. Mira Solis at 13:49 and 13:58, followed by contact with Blue Ember receiving at 14:07. Active cooling continued until departure at 14:18.

The carrier investigation attributes the event to an unenergized standby transition that was not positively verified, combined with the misdirected alert. Post-event testing did not identify a broken connector or a trailer incapable of frozen service. The exhibit distinguishes contemporaneous system entries from the later root-cause synthesis. It records operational history only and does not assign product-release authority to Granite Heron.

Integrity statement and evidentiary limits

The Granite Heron custodian compared this presentation with the retained custody record, device export, controller information, route file, and contact log. The plotted values preserve sampling order; the chronology identifies approximations where a witness or later investigation supplied the source. No correction overwrites an original timestamp. Supplemental explanations remain separately dated.

The event ended before the trailer left Fletcher, and delivery occurred after the monitor had returned within range. Those facts may be considered with the magnitude, duration, intended validation use, assay material, and September 16 disposition. They do not compel a finding that receiving caused the warming or that recovery conclusively restored suitability.

Granite Heron preserved the source export so a reader can distinguish recorded temperature from advocate characterization. The rendering is not raw device software, a stability study, or a machine interpretation of BE-214. Admission likewise does not resolve whether the excursion caused all claimed consequences. The custodian certified only that the collected records are the business and device records used to reconstruct shipment GHL-ASH-091224-087.