- A normal stator is used. - Arotor similar to an alternator is used. - The slip rings are replaced with an inductive transformer across the axis of the shatt, - The Inductive transformer is the only nethod of transferming gover to the rotor - An AC square vove is feel to the stationary The Amplitude is variable on the waveform, for variable torque. - Frequency Muill be ZOKhz of higher -Rotational Frequency will be loner: 0-500hz