
Individually Renovable Poles



Pole can be wound outside the stator much more simply. Then pole can be slid into place and wired to the other stator poles.