


EG1311: Design & Make

Part Modelling I




Dr. Jason S. Ku

Demo




Demo


Shaft





Piston





Link





Shaft





Shaft





Shaft




Shaft



Shaft



Shaft



shaft1 v1

Untitled*

1 of 10

JK

DESIGN

SOLID

SURFACE

MESH

SHEET METAL

TOOLS

CREATE

MODIFY

ASSEMBLE

CONSTRUCT

INSPECT

INSERT

SELECT

BROWSER

(Unsaved)

Document Settings

Named Views

Origin

Sketches

Unsaved: Changes may be lost

Save

360.0 deg

REVOLVE

Profile 1 selected

Axis 1 selected

Type Angle

Angle 360.0 deg

Direction One Side

Operation New Body



OK

Cancel



1 Profile 1 Sketch Line | Angle : 0.0 deg

Demo



Shaft





Link






Piston







Link



Link



shaft1 v1 shaft2 v1 Untitled* 2 of 10 JK

DESIGN ▾ SOLID SURFACE MESH SHEET METAL TOOLS

CREATE ▾ MODIFY ▾ ASSEMBLE ▾ CONSTRUCT ▾ INSPECT ▾ INSERT ▾ SELECT ▾

BROWSER ⚠ Unsaved: Changes may be lost Save

- (Unsaved)
- Document Settings
- Named Views
- Origin
- Sketches

EXTRUDE

Type:

Profiles: 4 selected

Start: Profile Plane ▾

Direction: Symmetric ▾

Extent Type: Distance ▾

Measurement:

Distance: 5

Taper Angle: 0.0 deg




Operation: New Body ▾

OK Cancel

7.00 mm



Multiple selections

Link





Demo


Shaft






Link






Piston






Piston






Piston



Piston





Piston





Demo



Shaft



Link



Piston



Practice

What is the minimum number of 2D sketches needed to model the Shaft example part from this lecture?

Respond at pollev.com/jku

A

B

C

D

A) 1

B) 2

C) 3

D) 4

EG1311: Design & Make

Part Modelling I

Dr. Jason S. Ku