
\$13040 Laser Engraving Machine



User Guide

Contents

Packing list1	
Assemble Manual3	
Package8	
Laser on Machine9	
Controller and Offline9	
Software Manual10	1
Offline Manual18	
FAQ/After-Sales service19	

Safety Guide



Caution: Avoid eye or skin exposure to direct radiation



Away from children



Always wear protective glasses when use the machine



Prohibited from use in flammable objects or gases.



In case of emergency, cut off the power immediately





Shutdown steps: When you are not using the machine, first cut off the power, then turn off the software, at last dial out the USB cable


Packing List						
001	Aluminum profile	2040V-510mm	2	Piece		
002	Aluminum profile	2040V-403mm	1	Piece		
003	Aluminum profile	2020-360mm	2	Piece		
004	Acrylic	PAMA-4050	1	Set		
005	Stepper motor	42HS34	3	Piece	5	
006	Synchronous belt	GT2-6mm	1.8	Meter	~	
007	Pulley	5mm	12	Piece	0	
008	Corner code	2028	4	Piece		
009	Controller	GRBL1.1	1	Piece	less of c	
010	Power source	12V 5A	1	Piece	- 55	
011	Hexagon socket cap screw	M5*8	16	Piece		
012	Hexagon socket cap screw	M5*12	4	Piece		
013	Hexagon socket cap screw	M5*20	12	Piece		
014	Hexagon socket cap screw	M5*30	8	Piece	-	
015	Hexagon socket cap screw	M5*50	4	Piece	-	
016	Hexagon socket cap screw	M3*12	12	Piece	-	
017	Slide nut	M5	8	Piece	4	
018	Self-Locking Nut	M5	12	Piece		
019	Square nut	M5	12	Piece	4	
020	Synchro wheel	GT2-20 5mm	3	Piece		


021	Copper nut	M5*6	8	Piece	
022	Copper nut	M5*8	8	Piece	
023	Socket wrenches	2/2.5/4/8	1	Set	777
024	Hand screw	M3*6	4	Piece	
025	Pan head screw	A:M3*12 B:M3*10	3	Piece	•
026	Laser wire	80cm	1	Piece	Ò
027	Stepper motor wire	60cm	3	Piece	
028	Screw box	/	1	Piece	
029	coil bobbin	8mm	2	Piece	
030	Aluminum cooling module	A/B	1	Piece	
031	USB flash drive	/	1	Piece	13.
032	Package	/	1	Piece	
15W Lifting module					
Acrylic		Thickness:8mm	1	Piece	The same
Hexagon socket cap screw		M3*12	4	Piece	
Optional					
0. 5W 1W		1.6W		2.5W	3. 5W
5. 5W 7W		10W		15W	

3040 Assemble Manual













Double Y axis motor

















Package




Controller and Port Define



2 Aixs 2.0



2 Aixs 4.0



S1-3040 Laser Engraving Machine





http://dwz.date/Ar3

Follow our Youtube channel to know more about Laser engraving machine!

10

20 -

30

40 -

50