

SYS\_STAT (0x00)

xx1x xxxx

Wait ~5s

check\_system

Clear faults SYS\_STAT (0x00)

bit 5 -> 1

SYS\_CTRL2 (0x05)

bits 0,1 -> 1

Return 0

Return 1