
WDM BULLETIN
No. 1828 (133/671) Ref. COA 34-1625

No	DATE	REFERENCE	CHG LTR	SIG.
②	JAN 22 '04	COA 34-1625	DJ-1	kamijo
①	JUL 10 '03	Transcript COA 34-1392	DJ-1	Momeda

BOEING

JAL 747 WIRING DIAGRAM



DRAFTED BY: ED ANDERSON
CHECKED BY:

NOTES:
1. HEADSET/BOOM MIC ASSEMBLY B408 NOT SHOWN
2. CAP AND STOW NEAR STA300

3. STA 408, WL 359, LBL 30 FOR 170, 173, 176-179 (RS001-RS002, RS255-RS258)
4. P8 STAND-PILOTS CONTROL FOR 179 (RS258). ALSO FOR 169, 173, 177-178 (RD227, RS255-RS258) AFTER INC OF SB 34-2757. (COA 34-1625 or -1630) ②
5. GD290-DC FOR 179 (RS258). ALSO FOR 169, 173, 177-178 (RD227, RS255-RS258) AFTER INC OF SB 34-2757. (COA 34-1625 or -1630) ②

DRAWING NO.: 61B74707
PAGE DATE: MAY 28/03
DCN: DJ -- 1
CHANGE:

'04. 5.06

AUDIO INTEGRATING-FLIGHT INTERPHONE-CAPTAIN

169-170, 173, 176-179

RD227 RS001-RS002
RS255-RS258

23-51-11
PAGE 5

D36950