


No. 1828 (133/671) Ref. 60A34-1625

No. 1828 (133/671) Ref. 60A34-1625



DRAFTED BY: ED ANDERSON
CHECKED BY:

NOTES:
1 HEADSET/BOOM MIC ASSEMBLY B408 NOT SHOWN

DRAWING NO.: 61B74707
PAGE DATE: MAY 28/03

DCN: DJ - 1
CHANGE:

3 STA 408, WL 359, LBL 30 FOR 170, 173, 176-179 (RS001-RS002, RS255-RS258)

4 P8 STAND-PILOTS CONTROL FOR 179 (RS258). ALSO FOR 169, 173, 177-178 (RD227, RS255-RS258) AFTER INC OF SB 34-2757. (C/A 34-1625 or -1630)

5 GD290-DC FOR 179 (RS258). ALSO FOR 169, 173, 177-178 (RD227, RS255-RS258) AFTER INC OF SB 34-2757. (COA 34-1625 or -1630) (2)

'04. 5.06

RD227 RS001-RS002
RS255-RS258

AUDIO INTEGRATING-FLIGHT
INTERPHONE-CAPTAIN

169-170, 173, 176-179

23-51-11
PAGE 5

③	JAN 22 '04	COA 34 - 1625	DJ-1	kam:j
⑦	JUL 10 '03	Transcript COA 34 - 1392	DJ-1	memorand
No	DATE	REFERENCE	CHG LTR	SIG.