







BOEING 747 JAL WIRING DIAGRAM

W043



P13 PANEL-SECOND OBSERVERS CONSOLE

NOTES:
1 R0227-R0229 (109)

2 STA 450, WL 350, LBL 85 FOR R0227-R0229 (109)
STA 479, WL 355, LBL 50 FOR R0266 (171)



LAST CHANGE DATE: 07-08-87
OPT INTS: TAG 707-BM

DRAWING NO: 61874707
PAGE DATE: JUL 27/87

DCN: 8N
CHANGE:

23-51-15
PAGE 4

FOR INTERNALS
SEE 23-51-11



AUDIO INTEGRATING-FLIGHT INTERPHONE-SECOND OBSERVER	
169-171, 173, 176-179	

R0227-R0229, R0255-R0258
R0001-R0010, R0266

23-51-15
PAGE 4