




JAL 747 WIRING DIAGRAM

②	JAN 22 '64	COA 34-1625	DJ-1	Kamijo
②	JUL 10 '63	Transcript CoA 34-1392	DJ-1	Mimoda
No	DATE	REFERENCE	CHG LTR	SIG.

DRAFTED BY: ED ANDERSON
CHECKED BY:

- NOTES:
- HEADSET/BOOM MIC ASSEMBLY B410 NOT SHOWN
 - CA7 AND STOW NEAR STA300

DRAWING NO: 61B74707
PAGE DATE: MAY 28/03DCN: DJ-1
CHANGE:

- ③ STA 408, WL 359, LBL 30 FOR 170, 173, 176-179 (RS001-RS002, RS255-RS258)
- ④ P8 STAND-PILOTS CONTROL FOR 179 (RS258). ALSO FOR 169, 173, 177-178 (RD227, RS255-RS258) AFTER INC OF SB 34-2757. (CoA 34-1625 or -1630)

- ⑤ GD31-DC FOR 179 (RS258). ALSO FOR 169, 173, 177-178 (RD227, RS255-RS258) AFTER INC OF SB 34-2757. (CoA 34-1625 or -1630)

23-51-12
PAGE 5AUDIO INTEGRATING-FLIGHT
INTERPHONE-FIRST OFFICER

169-170, 173, 176-179

RD227
RS255-RS258

RS001-RS002

23-51-12
PAGE 5