


BOEING 747 JAL WIRING DIAGRAM

①	JUL 22/87	Transcript COA 23-703	BM-1	Opata
No.	Date	Reference	CHG LTR	Sign

W297



NOTES:
1 STA 408, WL 359, LBL 30 FOR RS001-RS010, RS255-RS270 (170, 173, 176-179)
STA 479, WL 355, LBL 50 FOR RZ266 (171)

DRAWING NO: 61874707
PAGE DATE: APR 2/87
JUL 27/87

DCN: BM-1
CHANGE:

23-51-13
SH 1 PAGE 4

AUDIO INTEGRATING-FLIGHT
INTERPHONE-FLIGHT ENGINEER

169-171, 173, 176-179


RD227-RD229, R6255-R6270-RS255-RS258
RS001-RS010, RZ266

23-51-13
SH 1 PAGE 4

JAPAN AIR LINES

WIRING DIAGRAM

NO.	DATE	REFERENCE	CHG LTR	SIG.
①	FEB 25 '86	COA 23-703	JL	<i>Ogata</i>



DFTSM	CHECK	APPRV
<i>Ogata</i>		

DIAGRAM NO.	SHT	PAGE
23-51-13	2	4

TITLE: AUDIO INTEGRATING- FLIGHT INTERPHONE- FLIGHT ENGINEER	CHG LTR JL
EFFECTIVITY: 169, 170, 173, 176-179	DATE FEB 25 '86
DIAGRAM NO. 23-51-13	SHT 2
	PAGE 4