


BOEING 747
JAL WIRING DIAGRAM

②	Sep 28 '88	EFF CHG	BS-1	Ogata
①	AUG 01 '86	Transcript COA 24-331	BJ-1	Ogata
No.	Date	Reference	CHG LTR	Sign




NOTES:
154-155, 161-163, 166, 169-170, 173, 176-179, 212-213 (RD223-RD229, RS001-RS010, RS251-RS270). ALSO EFF FOR 145-150 (RD221-RD222) AFTER INC OF SB 24-2087.
183-187, 189, BS-1
DCH: BS-1
CHANGE.

DRAFTED BY
CHECKED BY

BRWING NO. 61874707
PAGE DATE: MAY-12/86
JUN 06/88

24-11-11
PAGE 3



INCORPORATES
COA 24-433 (SB 24-2087) FOR
149-150 (RD221-RD222)

GENERATOR DRIVE 1 AND 2	
RD221-RD229 RS001-RS010	RS251-RS270
149-150, 154-155, 161-163, 166, 169-170, 173, 176-179, 212-213, 183-187, 189	

24-11-11
PAGE 3