



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

To:

Simon Barclay
24 Bennelong Pl
EAST KURRAJONG NSW 2758

From:

KLR Automotive ABN 58 633 010 965
6 Sovereign Place
SOUTH WINDSOR, NSW 2756

Vehicle Rego: WYR294 **Invoice Date** 16/02/2023 **Invoice No:** 09960

Payment Terms: COD

TAX INVOICE**Labor:**

	Hours	Rate	Subtotal
Replace front propshaft			\$67.50
Replace airflow meter			\$135.00
Service; replaced fuel filter, oil filters, air cleaner			\$202.50
Checked gearbox; slight resistance in 3rd; replaced oil with 80 90/ATF mix			\$67.50
Checked throttle getting stuck; road tested approx 10kms couldn't find fault			\$67.50
Checked poor braking power; front and rear pads needed replacing, replaced and te			\$270.00
Checked radio no backlighting; removed radio and no power on light circuit, ran new			\$135.00
Replaced AM/FM antenna, tested all ok			\$135.00
Replaced rear shocks (Perentie)			\$135.00
Replaced healdights with LED			\$135.00
Replaced warn winch solenoid; cust supplied, issues with wiring, ran new wiring, tested all ok			\$405.00
			\$0.00
Total			\$1,755.00

Parts:

Part Number	Description	Qty	Per Unit	Subtotal
TVB100610	PROP,FRNT,110 V8,200/300 DISC,300 DEF	1	\$361.00	\$361.00
MHK100620	Air Flow Meter, TD5	1	\$75.00	\$75.00
GA4159	EBC Green Stuff Performance brake pads 110 Ft	1	\$178.00	\$178.00
SFP000280	BRAKE PADS, REAR DEF,Gen	1	\$50.00	\$50.00
KLR-SK001	Service Kit - Discovery 2/ Defender TD5	1	\$70.00	\$70.00
LY7	LED Headlight Insert; inc Park/Indicator	1	\$200.00	\$200.00
RNF100090L	BUSH, DAMPER	4	\$5.18	\$20.72
BYG4000	SHOCK ABSORBER, 110 REAR MILT.	2	\$185.40	\$370.80
NRC4365	WASHER, SHOCK ABSORBER MOUNT	4	\$1.82	\$7.28
AMR2014	AERIAL, RADIO, DISCOVERY	1	\$75.00	\$75.00
Total				\$1,407.80



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

Note:

Subtotal	\$3,162.80
GST	\$316.28
Invoice Total	\$3,479.08
Total Payments	\$702.35
Amount Due	\$2,776.73

*Why not pay by phone? We accept most major credit cards - Or - by Direct
Deposit To KLR Automotive BSB 012 874 A/C 472434595*