



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

To:

Simon Barclay
24 Bennelong Pl
EAST KURRAJONG NSW 2758

From:

KLR Automotive ABN 58 633 010 965
6 Sovereign Place
SOUTH WINDSOR, NSW 2756

Vehicle Rego: WYR294

Invoice Date 29/09/2022

Invoice No: 09960

Payment Terms: COD

TAX INVOICE

Labor:

	Hours	Rate	Subtotal
Replace front propshaft			\$67.50
Replace airflow meter			\$135.00
Total			\$202.50

Parts:

Part Number	Description	Qty	Per Unit	Subtotal
TVB100610	PROP,FRNT,110 V8,200/300 DISC,300 DEF	1	\$361.00	\$361.00
MHK100620	Air Flow Meter, TD5	1	\$75.00	\$75.00
Total				\$436.00

Note:

Subtotal	\$638.50
GST	\$63.85
Invoice Total	\$702.35
Total Payments	\$702.35
Amount Due	\$0.00

Why not pay by phone? We accept most major credit cards - Or - by Direct
Deposit To KLR Automotive BSB 012 874 A/C 472434595