

**KLR Automotive****Phone:** +61245775010**Email:** service@klr.com.au**Web:** <http://klr.com.au>**ABN:** 58633010965

Invoice

INV6976

Date: 05/11/2025**Bill To**

Simon Barclay
Simon Barclay
UNIT 7, 140 FRANCIS STREET
RICHMOND NSW 2753
Australia

Ship To

Simon Barclay
UNIT 7, 140 FRANCIS STREET
RICHMOND NSW 2753
Australia

Terms	Due Date	Vehicle (Automotive)	Mileage
Payment Prior to Delivery	05/11/2025	SALLDHA87XA176069	309,552

Item	Quantity	Units	Rate	Amount
SFP000280 Rear Brake Pads, Defender to 2001 Rear Brake Pads, Defender To 2001	1	EA	\$60.00	\$60.00
STC1268 Defender Right Hand Rear Brake Calliper >'01 Defender Right Hand Rear Brake Calliper >'01	1	EA	\$171.82	\$171.82
STC1269 Defender Left Hand Rear Brake Calliper >'01 Defender Left Hand Rear Brake Calliper >'01	1	EA	\$171.82	\$171.82
LR018026 Rear Brake Disc, Solid, Defender Rear Brake Disc, Solid, Defender	2	EA	\$79.00	\$158.00
PGG500340 Puma 2.4/Td5 Fan and Hub Assembly Puma 2.4 Fan And Hub Assembly	1	EA	\$185.91	\$185.91
ERR6949 Bracket And Pulley Assy, Td5 Bracket And Pulley Assy, Td5	1	EA	\$87.27	\$87.27
PQS101490 Td5 Ancillary Drive Belt, NO Aircon, NO ACE Td5 Ancillary Drive Belt, No Aircon, No Ace	1	EA	\$33.09	\$33.09
Labour Labour Charge Rear Brake noise/ strip rear brakes, replace both hub seals with later double lip style, grease wheel bearings, replace both calipers, replace brake pads, bleed system as required, road test, no further issues.	2	Hr	\$175.00	\$350.00
Labour Labour Charge Check starting issue, vehicle did not play up for first few weeks of starting, remove belt to check if potential seizing pulley, one idler notchy, replace with new pulley and bearing, fan hub slight movement, replace fan hub, install new drive belt. identified issue with starting, found getting 12volts to starter but not engaging, install new terminal, to confirm no connection issues, has not faulted again. If problem reoccurs will require new starter motor.	2	Hr	\$175.00	\$350.00

Bank Account Details:

Account Name: KLR Automotive PTY LTD
BSB: 012874
Account #: 472434595

Subtotal \$1,567.91**GST Total** \$156.79**AUD Total** **\$1,724.70****Balance** **\$1,724.70**

INV6976



KLR Automotive

Phone: +61245775010

Email: service@klr.com.au

Web: <http://klr.com.au>

ABN: 58633010965

Invoice

INV6976

Date: 05/11/2025

Customer Notes:



Pay with the QR code, or click this [secure link](#). You can also copy the link to clipboard.



INV6976