

The Macquarie Motors Group Pty Ltd

ACN 002 047 903

TAX INVOICE

Hyundai

Land Rover

Range Rover

VEHICLE SALES, SERVICE, PARTS

128 RUSSELL STREET, BATHURST 2795

VEHICLE SALES

105 STEWART STREET, BATHURST 2795


PO BOX 746, BATHURST NSW 2795

Phone (02) 6331 3422 • Fax (02) 6331 9757

ABN 25 002 047 903

REPAIR INVOICE No.		R 6223		CW	
		ORDER No.		ACCOUNT CODE	
NAME & ADDRESS	MR SIMON BARCLAY			TIME IN	
	24 BENNELONG PLACE			TIME REQ'D	
	EAST KURRAJONG 2758			0292837401	
		NOTIFY PHONE			
22-JUN-01	DEFENDE	WYR294	WHITE	19012	A176069
DATE OF REPAIR	MAKE	REGO No.	COLOUR	KILOMETRES	CHASSIS No.

PART NUMBER	DESCRIPTION	CODE	TAX	QTY	CUST.
ERR6299	FILTER ROTOR	18	2	1	35.57
GLOBE		21	2	1	11.66

CODE	DESCRIPTION	TYPE	CONTROL	SALE \$ c	DESCRIPTION	\$ c
T	20,000 KM SERVICE	R		138.38	TOTAL PARTS	47.23
T	CHECK GEARS GRATING INTO 3RD	W			TOTAL LABOUR	138.38
T	CHECK JERKING IN 1ST & 2ND GEARS ON ROUGH ROADS	W			TOTAL SUBLET	0.00
T	CHECK ENGINE LOOSES POWER AT 80-100 KPH	W			TXT SOFTEC E/O	51.00
T	CHECK ENGINE ACCELERATING & DEACCELERATING BY ITSELF	W			SUPPLIES & ENVI	4.00
T	CHECK ENGINE FEELS LIKE IT IS NOT GETTING ENOUGH FUEL	W				
T	CHECK FUEL CONSUMPTION	W				
T	CHECK TRANSMISSION WHINE	W				
T	CHECK SHIFT WHEN COLD DOWN TO SECOND & UP TO 3RD	W				
PAID 					TOTAL GST	24.06
					TOTAL	264.65
					I authorise the abovementioned repairs to be executed as soon as possible. I agree to pay the necessary charges upon completion of the repairs. Should any further repairs be necessary, please phone me prior to commencement of these repairs for permission to proceed.	
					Signature of Owner or Agent	

Vin # SALLDHA87XA176069 Sale date 25-NOV-00