



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

To:

Simon Barclay
24 Bennelong Pl
EAST KURRAJONG NSW 2758

From:

KLR Automotive ABN 58 633 010 965
6 Sovereign Place
SOUTH WINDSOR, NSW 2756

Vehicle Rego: DGA08D **Invoice Date** 28/06/2022 **Invoice No:** 09889

Payment Terms: COD

TAX INVOICE

Labor:

	<i>Hours</i>	<i>Rate</i>	<i>Subtotal</i>
Service as required; change engine oil and filter; replace air filter			\$202.50
Replace heater illumination globe; fit Perentie ignition barrel			\$270.00
Replace rear lower shock bushes			\$94.50
Total			\$567.00

Parts:

<i>Part Number</i>	<i>Description</i>	<i>Qty</i>	<i>Per Unit</i>	<i>Subtotal</i>
BLITZ	Blitz Windscreen Washer Additive, 32ml	1	\$8.00	\$8.00
EL	Environmental Levy, Workshop Sundries	1	\$11.00	\$11.00
HPRC4	OIL, PENRITE ENVIRO+ C-4, 5W/30, FULL SYN	6	\$16.95	\$101.70
LR030778	Filter, Oil, Duratorq 2.2, Def+FLNDR	1	\$21.00	\$21.00
PHE500060	Air Filter, Defender '07>	1	\$59.00	\$59.00
VPLDS0147	Defender Floor Mat Set, Front, '07>	1	\$145.00	\$145.00
QRF100870	STEERING LOCK ASS'LY, 110 DIESEL	1	\$126.36	\$126.36
RNF100090L	BUSH, DAMPER	4	\$5.21	\$20.84
Total				\$492.90

Note:

Transfer case intermediate shaft oil leak

Subtotal	\$1,059.90
GST	\$105.99
Invoice Total	\$1,165.89
Total Payments	
Amount Due	\$1,165.89

Why not pay by phone? We accept most major credit cards - Or - by Direct
Deposit To KLR Automotive BSB 012 874 A/C 472434595