



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

To:

Simon Barclay
24 Bennelong Pl
EAST KURRAJONG NSW 2758

From:

KLR Automotive ABN 58 633 010 965
6 Sovereign Place
SOUTH WINDSOR, NSW 2756

Vehicle Rego: DGA08D

Invoice Date 4/07/2023

Invoice No: 10194

Payment Terms: COD

TAX INVOICE**Labor:**

	Hours	Rate	Subtotal
Carried out service as required, replaced engine oil and filter, replaced			\$0.00
air filter, checked all oil levels, drained and replaced transfer case oil.			\$262.50
Vehicle jumping out of high range, will need to remove transfer case and			\$0.00
inspect, intermediate shaft is leaking badly.			\$35.00
replaced door lock in drivers door to match ignition.			\$87.50
Total			\$385.00

Parts:

Part Number	Description	Qty	Per Unit	Subtotal
EL	Environmental Levy, Workshop Sundries	1	\$11.00	\$11.00
HPRC4	OIL, PENRITE ENVIRO+ C-4, 5W/30, FULL SYN	6	\$16.95	\$101.70
LR030778	Filter, Oil, Duratorq 2.2, Def+FLNDR	1	\$21.00	\$21.00
PHE500060	Air Filter, Defender '07>	1	\$59.00	\$59.00
HPR90	Oil, Penrite 80/90 EP Gear	2.5	\$16.95	\$42.38
PINK	Pink Slip (inc inspection)	1	\$40.00	\$40.00
Total				\$275.08

Note:

Subtotal	\$660.08
GST	\$66.01
Invoice Total	\$726.09
Total Payments	
Amount Due	\$726.09

Why not pay by phone? We accept most major credit cards - Or - by Direct
Deposit To KLR Automotive BSB 012 874 A/C 472434595