



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

To:

Simon Barclay
24 Bennelong Pl
EAST KURRAJONG NSW 2758

From:

KLR Automotive ABN 58 633 010 965
6 Sovereign Place
SOUTH WINDSOR, NSW 2756

Vehicle Rego: DGA08D **Invoice Date** 7/07/2023 **Invoice No:** 10195

Payment Terms: COD

TAX INVOICE**Labor:**

	<i>Hours</i>	<i>Rate</i>	<i>Subtotal</i>
Check engine light coming on and vehicle going into limp mode,			\$0.00
Replaced air flow meter, Fault still evident, Found intercooler split			\$0.00
removved intercooler and replaced with new component, cleared faults,			\$0.00
road tested vehicle, no further faults.			\$525.00
Total			\$525.00

Parts:

<i>Part Number</i>	<i>Description</i>	<i>Qty</i>	<i>Per Unit</i>	<i>Subtotal</i>
LR017950	INTERCOOLER; DEF TD5 AND PUMA	1	\$331.81	\$331.81
MHK501040-E	AIR FLOW METER; PUMA&FL2	1	\$115.86	\$115.86
Total				\$447.67

Note:

Subtotal	\$972.67
GST	\$97.27
Invoice Total	\$1,069.94
Total Payments	
Amount Due	\$1,069.94

Why not pay by phone? We accept most major credit cards - Or - by Direct
Deposit To KLR Automotive BSB 012 874 A/C 472434595