



5/62 Argyle St
South Windsor NSW 2756
P (02) 4577 5010 F (02) 4577 5018

To:

Simon Barclay
Unit 7, 140 Francis Street
RICHMOND NSW 2753

From:

KLR Automotive ABN 58 633 010 965
6 Sovereign Place
SOUTH WINDSOR, NSW 2756

Vehicle Rego: DGA08D **Invoice Date** 5/06/2024 **Invoice No:** 10462

Payment Terms: COD

TAX INVOICE

Labor:

	<i>Hours</i>	<i>Rate</i>	<i>Subtotal</i>
Carried out service, replaced engine oil and filter, replaced air filter, checked all tyre pressures.			\$0.00
Carried out pink slip			\$262.50
Check electrical issues, losing power at random times, checked all grounds under vehicle, all ok, found bulletin relating to similar issues,			\$41.81
removed fuse board under seat, cleaned all grounds, cleaned main power into fuse box, reconnected battery, no further faults evident.			\$0.00
			\$0.00
			\$700.00
Total			\$1,004.31

Parts:

<i>Part Number</i>	<i>Description</i>	<i>Qty</i>	<i>Per Unit</i>	<i>Subtotal</i>
HPRC4	OIL, PENRITE ENVIRO+ C-4, 5W/30, FULL SYN	6	\$16.95	\$101.70
LR030778	Filter, Oil, Duratorq 2.2, Def+FLNDR	1	\$21.00	\$21.00
PHE500060	Air Filter, Defender '07>	1	\$59.00	\$59.00
Total				\$181.70

Note:

Subtotal	\$1,186.01
GST	\$118.60
Invoice Total	\$1,304.61
Total Payments	
Amount Due	\$1,304.61

Why not pay by phone? We accept most major credit cards - Or - by Direct Deposit To KLR Automotive BSB 012 874 A/C 472434595