

**KLR Automotive****Phone:** +61245775010**Email:** service@klr.com.au**Web:** <http://klr.com.au>**ABN:** 58633010965

Invoice

INV6975

Date: 05/11/2025**Bill To**

Simon Barclay
Simon Barclay
UNIT 7, 140 FRANCIS STREET
RICHMOND NSW 2753
Australia

Ship To

Simon Barclay
UNIT 7, 140 FRANCIS STREET
RICHMOND NSW 2753
Australia

Terms	Due Date	Vehicle (Automotive)	Mileage
Payment Prior to Delivery	05/11/2025	SALLDWBR7CA423699	164,949

Item	Quantity	Units	Rate	Amount
PHE500060 Defender (Puma) Air Filter Defender (Puma) Air Filter	1	EA	\$24.09	\$24.09
LR030778 Oil Filter, Tdci 2.2l Oil Filter, Tdci 2.2L	1	EA	\$13.55	\$13.55
BTD1 BTD/Non-Stock Item ENGINE PIPE	1		\$575.45	\$575.45
Labour Labour Charge REMOVE AND FIT SUPPLIED UPGRADE ENGINE PIPE	3.1	Hr	\$175.00	\$542.50
Labour Labour Charge Warning Lights coming on dash relating to EGR/ boost control issues, check all wiring over transfer case to fuse box, check engine bay wiring, carry out software upgrades relating to EGR, Road test vehicle, no further faults/ limp mode	5	Hr	\$175.00	\$875.00
C15W30 Engine Oil, Synthetic 5W30 Engine Oil, Synthetic 5W30	6.5	EA	\$19.95	\$129.68
Labour Labour Charge Carry out service, replace engine oil and filter, replace air filter, check all fluids.	1.2	Hr	\$175.00	\$210.00

Bank Account Details:

Account Name: KLR Automotive PTY LTD
BSB: 012874
Account #: 472434595

Subtotal \$2,370.27**GST Total** \$237.03**AUD Total** **\$2,607.30****Balance** **\$2,607.30****Customer Notes:**Pay with the QR code, or click this [secure link](#). You can also copy the link to clipboard.

INV6975