De Young Properties

All Defects	Lot 35/Trac	Lot 35/Tract 6164			
Anlin Windows					
Code: ZZ_2028 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Window cracked in great room	Incomplete		
Cabinet Connection					
Code: ZZ_2021 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Touch up cabinets in kitchen	Incomplete		
Code: ZZ_2022 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Please adjust doors and drawers in kitchen	Incomplete		
Code: ZZ_2023 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Please address cabinet scratches in bath 3	Incomplete		
Code: ZZ_2024 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Please adjust cabinets in bath 3	Incomplete		
Code: ZZ_2035 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet touch up in laundry room	Incomplete		
Code: ZZ_2037 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Adjust drawers in master bath	Incomplete		
California Building Products					

All Defects	Lot 35/Trac	Lot 35/Tract 6164		
Code: ZZ_2029 Category: Fireplace Unit Partner: California Building Products	Location: Type:	Description: Fireplace won't start	Incomplete	
Citadel Roofing and Solar				
Code: ZZ_2026 Category: Roofing Partner: Citadel Roofing and Solar	Location: Type:	Description: Solar not finished	Incomplete	
Elia Painting				
Code: ZZ_2030 Category: Paint Partner: Elia Painting	Location: Type:	Description: Touch up paint in entry	Incomplete	
Code: ZZ_2031 Category: Paint Partner: Elia Painting	Location: Type:	Description: Touch up in stairwell	Incomplete	
Code: ZZ_2033 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up in bath 2	Incomplete	
Code: ZZ_2034 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up in bed 3	Incomplete	
HSI				
Code: ZZ_2036 Category: Fire Sprinklers Partner: HSI	Location: Type:	Description: Missing fire sprinkler cap in master bed	Incomplete	
Partner: HSI Matthews Quality Construction	,,			

All Defects	Lot 35/Trac	Lot 35/Tract 6164		
Code: ZZ_2027 Category: Millwork Partner: Matthews Quality Construction	Location: Type:	Description: Adjust door to garage won't close automatically	Incomplete	
Ohanians Drywall				
Code: ZZ_2032 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall touch up in bed 2	Incomplete	
Quality Plumbing				
Code: ZZ_2025 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Water heater not plugged in	Incomplete	
Code: ZZ_2038 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Finish install of plumbing in master bath	Incompleto	
Tri Valley Plastering & Drywall				
Code: ZZ_2020 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Stucco touch up by outlet on patio	Incomplete	
Code: ZZ_2039 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Stucco touch up around footing of home	Incomplete	
Code: ZZ_2040 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Fog Match exterior color	Incomplete	