De Young Properties

All Defects	Lot 7/Tract 6260		
Anlin Windows			
Code: ZZ_947 Category: Windows Partner: Anlin Windows	Location: Bedroom 3 Type: Window frame scratched/chipped/dented	Description: Window scratches in several spots on both windows in bedroom 3	Incomplete
Code: ZZ_967 Category: Windows Partner: Anlin Windows	Location: Bathroom 1 Type: Window frame scratched/chipped/dented	Description: Window screen next to shower in master bath is ripped	Incomplete
Code: ZZ_984 Category: Windows Partner: Anlin Windows	Location: Bedroom 4 Type: Window operation	Description: Window lock broken in bedroom 4	Incomplete
Code: ZZ_987 Category: Windows Partner: Anlin Windows	Location: Flex Super Great Room Type: Window operation	Description: Window in great room to backyard lock is not working	Incomplete
Code: ZZ_990 Category: Windows Partner: Anlin Windows	Location: Type: Window operation	Description: Slide and glide all windows and sliders around whole house	Incomplete
Code: ZZ_991 Category: Windows Partner: Anlin Windows	Location: Dining Room Type: Window operation	Description: Right side dining room window very difficult to open and close	Incomplete

All Defects	Lot 7/Tract 6260		
Code: ZZ_951 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Dent(s), ding(s), scratch(es)	Description: Bathroom 2 vanity cabinet has various chips inside and on top of some of the doors - please check inside for tape	Incomplete
Code: ZZ_952 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Adjust door(s)	Description: Additional lower cabinet in bath 2 has nail holes and chips, top drawer doesn't open - it's hitting the bottom door Top of the bottom door has a big chip	Incomplete
Code: ZZ_964 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Dent(s), ding(s), scratch(es)	Description: Cabinet vanity next to master tub needs touch up in several spots - check tops of doors and drawers	Incomplete
Code: ZZ_966 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Dent(s), ding(s), scratch(es)	Description: Vanity cabinets next to shower have a few chips - also bottom right side drawer needs to be adjusted	Incomplete
Code: ZZ_973 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Adjust door(s)	Description: Vanity cabinet next to shower top left drawer needs to be adjusted	Incomplete
Code: ZZ_975 Category: Cabinets Partner: Cabinet Connection	Location: Master Closet Type: Dent(s), ding(s), scratch(es)	Description: In master closet The cabinets need a lot of touch up - various scratches and chips and a hole by the outlet in the upper shelves Check inside and outside	Incomplete
Code: ZZ_980 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 3 Type: Dent(s), ding(s), scratch(es)	Description: Couple scratches and chips on vanity cabinets	Incomplete
Code: ZZ_986 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Dent(s), ding(s), scratch(es)	Description: Cabinet in laundry room down stairs	Incomplete

All Defects	Lot 7/Tract 6260		
Code: ZZ_994 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Oven frame has several scratches including top of drawer under oven, green stain inside the upper cabinet on ceiling of cabinet and on sides of oven frame	Incomplete
Code: ZZ_995 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Cabinets to the left of the cook top Lowers have a drawer with some chips on top and the upper closest to cook top has a chip inside	Incomplete
Code: ZZ_996 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Adjust door(s)	Description: Door under the cooktop on the left side needs to be adjusted	Incomplete
Code: ZZ_997 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Drawer on right side of cook top has chip on top Check lazy Susan shelves they seem to be hitting something when you try to turn them Upper cabinet has chips on side	Incomplete
Code: ZZ_998 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Island drawer cabinet tops need touch up	Incomplete
Citadel Roofing ar	nd Solar		
Code: ZZ_961 Category: Roofing Partner: Citadel Roofing and Solar	Location: Exterior Type: Cracked/broken/chipped roof tile(s)	Description: Clean off debris from roof - visible from some windows Check roof for broken tiles and clean off any debris	Incomplete
Everlast Paint			
Code: ZZ_948 Category: Paint Partner: Everlast Paint	Location: Bedroom 3 Type: Cleanup	Description: Bedroom3 walk-in closet needs paint touch up in several places including the underside of the shelves, millwork needs sanding and paint touch up in a few spots and wall above the door	Incomplete

All Defects	Lot 7/Tract 6260		
Code: ZZ_949 Category: Paint Partner: Everlast Paint	Location: Bedroom 3 Type: Cleanup	Description: Bedroom 3 needs paint touch up in several spots including the baseboard where there's a large chip, the interior of h tub r bedroom door and the trim around the door to the hallway and closet door	Incomplete
Code: ZZ_950 Category: Paint Partner: Everlast Paint	Location: Bedroom 3 Type: Cleanup	Description: The trim around the door to bedroom 3 needs to be caulked on bo to sides and painted Left side paint on wall has many bubbles Trim itself needs touch up	Incomplete
Code: ZZ_953 Category: Paint Partner: Everlast Paint	Location: Bathroom 2 Type: Cleanup	Description: Paint touch up needed in several places including window sill needs clean up - around the door trim to the bathroom needs touch up in several spots - check inside and outside door and trim Side of door has chip	Incomplete
Code: ZZ_955 Category: Paint Partner: Everlast Paint	Location: Bathroom 2 Type: Cleanup	Description: All around tub surround there needs to be caulking and paint touch up There's a couple small drywall cracks as well Check all around tub surround Also lots of bubbled paint	Incomplete
Code: ZZ_956 Category: Paint Partner: Everlast Paint	Location: Bathroom 2 Type: Cleanup	Description: Caulking around bath 2 tile to baseboard needs clean up	Incomplete
Code: ZZ_957 Category: Paint Partner: Everlast Paint	Location: Bedroom 2 Type: Cleanup	Description: Paint touch up needed in bedroom 2 including the door trim around the bedroom door and the trim around the closet door Drywall line on wall and inside the closet in several places	Incomplete
Code: ZZ_958 Category: Paint Partner: Everlast Paint	Location: Laundry Room Type: Cleanup	Description: Inside the laundry closet upstairs the painters did not finish caulking and painting the baseboard on the side of the stacked washer unit	Incomplete
Code: ZZ_959 Category: Paint Partner: Everlast Paint	Location: Laundry Room Type: Cleanup	Description: Laundry room upstairs needs touch up in several places Look inside including inside and outside door trim	Incomplete

All Defects	Lot 7/Tract 6260		
Code: ZZ_960 Category: Paint Partner: Everlast Paint	Location: Bedroom 1 Type: Cleanup	Description: Trim around the hallway upstairs - top of stairs and outside the bedroom doors needs touch up in several places	Incomplete
Code: ZZ_971 Category: Paint Partner: Everlast Paint	Location: Bathroom 1 Type: Cleanup	Description: Inside the toilet room needs paint touch up in several spots including behind the door and door trim and the top corner of door Check drywall above toilet too	Incomplete
Code: ZZ_976 Category: Paint Partner: Everlast Paint	Location: Master Closet Type: Cleanup	Description: Millwork inside master closet needs to be sanded and painted in several places	Incomplete
Code: ZZ_977 Category: Paint Partner: Everlast Paint	Location: Master Closet Type: Cleanup	Description: Paint touch up needed in several places in master closet including the baseboards	Incomplete
Code: ZZ_978 Category: Paint Partner: Everlast Paint	Location: Bathroom 3 Type: Cleanup	Description: Paint touch up needed in bath 3 Around the shower surround missing caulking Bubbling paint above shower Clean up needed around the contact wiring at window doe Check door trim area as well	Incomplete
Code: ZZ_979 Category: Paint Partner: Everlast Paint	Location: Bathroom 3 Type: Cleanup	Description: Paint touch up needed inside door trim and to the right of door by the door to the hathroom	Incomplete
Code: ZZ_981 Category: Paint Partner: Everlast Paint	Location: Entryway Type: Cleanup	Description: Paint touch up needed around all door frames by entry - door way to bath 3, door way to coat closet and doorway to bedroom 4 Also inside of coat closet - check around inside And top of bullnose by bath 3	Incomplete
Code: ZZ_982 Category: Paint Partner: Everlast Paint	Location: Bedroom 4 Type: Cleanup	Description: Bedroom 4 closet needs drywall and paint touch up - look around base of wall there's some damage there Check door trim inside of the closet and shelf	Incomplete

All Defects	Lot 7/Tract 6260		
Code: ZZ_983 Category: Paint Partner: Everlast Paint	Location: Bedroom 4 Type: Cleanup	Description: Paint touch up needed in several spots in bedroom 4 especially around the base boards	Incomplete
Code: ZZ_985 Category: Paint Partner: Everlast Paint	Location: Laundry Room Type: Cleanup	Description: Paint touch up needed around family entry door trim and laundry door trim	Incomplete
Code: ZZ_989 Category: Paint Partner: Everlast Paint	Location: Great Room Type: Cleanup	Description: Paint and drywall touch up needed in several places including chips in baseboards	Incomplete
Code: ZZ_999 Category: Paint Partner: Everlast Paint	Location: Kitchen Type: Cleanup	Description: Inside the pantry needs paint touch up and sanding in several spots	Incomplete
Fenceworks			
Code: ZZ_1001 Category: Fence Partner: Fenceworks	Location: Backyard Type:	Description: Missing gate on the left side 2 planks need to be replaced	Incomplete
Ferguson			
Code: ZZ_992 Category: Appliances Partner: Ferguson	Location: Kitchen Type:	Description: Oven and microwave done have power or aren't turning on	Incomplete
Code: ZZ_993 Category: Appliances Partner: Ferguson	Location: Kitchen Type:	Description: Check hood vent Seems to only be working on one side	Incomplete

All Defects	Lot 7/Tract 6260		
Code: ZZ_969 Category: Shower Door & Mirror Partner: Fresno Shower Door & Mirror	Location: Bathroom 1 Type:	Description: Shower glass stripping inside corner of master is not fully attached and there is excess silicone Needs to be fully attached and silicone cleaned up	Incomplete
Granite Mountain	Stone Design		
Code: ZZ_965 Category: Solid Surface Partner: Granite Mountain Stone Design	Location: Bathroom 1 Type:	Description: Caulking at backsplash in vanity by bath tub needs touch ip	Incomplete
Code: ZZ_974 Category: Solid Surface Partner: Granite Mountain Stone Design	Location: Bathroom 1 Type:	Description: Caulking at master sink -in between vanities needs touch ip	Incomplete
John Ventresca Co	0		
Code: ZZ_988 Category: Fireplace Surround Partner: John Ventresca Co	Location: Great Room Type: Mortar cracked/missing	Description: Mortar around the fireplace on both sides has cracks in several places and there's missing grout on the flex great room side	Incomplete
Landscape Conne	ection		
Code: ZZ_1000 Category: Landscaping Partner: Landscape Connection	Location: Backyard Type:	Description: Drain in side yard near HVAC condenser side need to be capped off	Incomplete
LinkUs			

All Defects	Lot 7/Tract 6260		
Code: ZZ_946 Category: Low Voltage Electrical Partner: LinkUs	Location: Bedroom 3 Type:	Description: Bedroom 3 window contacts need to be repaired at both windows	Incomplete
Code: ZZ_963 Category: Low Voltage Electrical Partner: LinkUs	Location: Bathroom 1 Type:	Description: Window in master by bath tub contact needs to be reinstalled	Incomplete
Ohanians Drywall			
Code: ZZ_970 Category: Drywall Partner: Ohanians Drywall	Location: Bathroom 1 Type: Texture issue	Description: Drywall and paint touch up needed around the window and master shower	Incomplete
Quality Plumbing			
Code: ZZ_962 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 1 Type:	Description: Master bath tub missing caulking in several places	Incomplete
Tile Interiors			
Code: ZZ_954 Category: Tile Partner: Tile Interiors	Location: Bathroom 2 Type: Grout cracked/missing	Description: Grout touch up needed next to bath tub	Incomplete
Code: ZZ_968 Category: Tile Partner: Tile Interiors	Location: Bathroom 1 Type: Grout cracked/missing	Description: Tile in master shower needs touch up including missing grout, and pencil marks and paint clean up	Incomplete

All Defects	Lot 7/Tract 6260		
Code: ZZ_972	Location: Bathroom 1		
Category: Tile		Description: Vanity area next to shower needs grout filled in several places	Incomplete
Partner: Tile Interiors	Type: Grout cracked/missing	needs grout mied in several places	
Tri Valley Plasterir	ng & Drywall		
Code: ZZ_1002		Description: Footing needs stucco touch	
Category: Stucco	Location: Backyard	up by patio and in side of house by HVAC condenser Also missing stucco at roof live	Incomplete
Partner: Tri Valley Plastering & Drywall	Type: Dash blotchy	by condenser And by the man door - both sides have huge gaps	, p
Code: ZZ_1002			
Category: Stucco	Location: Backyard	Description: Footing needs stucco touch up by patio and in side of house by HVAC	Incomplete
Partner: Tri Valley Plastering & Drywall	Type:	condenser Also missing stucco at roof live by condenser	mcomplete