De Young Properties

All Defects	Lot 24/Trac	Lot 24/Tract 6100			
Cabinet Connection					
Code: ZZ_4033 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet touch up on right vanity door in master bath	Incomplete		
Code: ZZ_4034 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet touch up on center drawer in master bath	Incomplete		
Code: ZZ_4038 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratch on lower drawer right of oven	Incomplete		
Code: ZZ_4039 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches on drawer faces left of oven	Incomplete		
Code: ZZ_4040 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Crown molding seam is very visible	Incomplete		
Elia Painting					
Code: ZZ_4030 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up under kitchen island	Incomplete		
Code: ZZ_4035 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up on corners of walls in master closet	Incomplete		
Fenceworks					

All Defects	Lot 24/Tract 6100			
Code: ZZ_4043 Category: Fence Partner: Fenceworks	Location: Type:	Description: Finish install of fence	Incomplete	
Ideal Custom Tile				
Code: ZZ_4027 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Fill grout by door trim by bed 3	Incomplete	
Code: ZZ_4028 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Missing grout in laundry room	Incomplete	
Code: ZZ_4029 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Fill grout by fridge surround	Incomplete	
Code: ZZ_4041 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Grout missing by kitchen island	Incomplete	
Code: ZZ_4044 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Grout missing by bath 2 door jamb	Incomplete	
Matthews Quality Construction				
Code: ZZ_4025 Category: Millwork Partner: Matthews Quality Construction	Location: Type:	Description: Divot on baseboard in bath 2	Incomplete	
Ohanians Drywall				

All Defects	Lot 24/Tract 6100			
Code: ZZ_4022 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall repair in bed 3	Incomplete	
Code: ZZ_4036 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall touch up in master bath water closet by light switch	Incomplete	
Code: ZZ_4037 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall touch up above master shower	Incomplete	
Westech				
Code: ZZ_4023 Category: Electrical Partner: Westech	Location: Type:	Description: Missing light in bed 3	Incomplete	
Code: ZZ_4024 Category: Electrical Partner: Westech	Location: Type:	Description: Missing light fixture in bath 2	Incomplete	
Code: ZZ_4026 Category: Electrical Partner: Westech	Location: Type:	Description: Missing light fixture in bed 2	Incomplete	
Code: ZZ_4031 Category: Electrical Partner: Westech	Location: Type:	Description: Missing light fixture in master bedroom	Incomplete	
Code: ZZ_4032 Category: Electrical Partner: Westech	Location: Type:	Description: Missing vanity lights in master bathroom	Incomplete	
Code: ZZ_4042 Category: Electrical Partner: Westech	Location: Type:	Description: Missing carriage lights on either side of garage	Incomplete	