De Young Properties

All Defects	Lot 6/Tract 6260		
Anlin Windows			
Code: ZZ_641 Category: Windows Partner: Anlin Windows	Location: Courtyard Type:	Description: Missing screens in courtyard	Incomplete
Code: ZZ_650 Category: Windows Partner: Anlin Windows	Location: Bathroom 2 Type:	Description: Missing screen in bath 2	Incomplete
Code: ZZ_665 Category: Windows Partner: Anlin Windows	Location: Bedroom 4 Type:	Description: Missing screen in bed 4	Incomplete
Cabinet Connection			
Code: ZZ_639 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type:	Description: White screw in grey extended cabinet on island	Incomplete
Code: ZZ_642 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Finish cabinet trim in whole home	Incomplete
Code: ZZ_656 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Trim unfinished in laundry	Incomplete
Code: ZZ_659 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Part missing	Description: Trim in master bath is missing	Incomplete

All Defects	Lot 6/Tract 6260		
Everlast Paint			
Code: ZZ_644 Category: Paint Partner: Everlast Paint	Location: Kitchen Type:	Description: Caulk crown molding on either side of hood	Incomplete
Code: ZZ_648 Category: Paint Partner: Everlast Paint	Location: Bedroom 2 Type: Cleanup	Description: 5 locations of paint drips in bed 2	Incomplete
Code: ZZ_649 Category: Paint Partner: Everlast Paint	Location: Stairwell Type: Cleanup	Description: Uneven paint on trim in stairwell	Incomplete
Code: ZZ_652 Category: Paint Partner: Everlast Paint	Location: Type:	Description: Paint touch up by outlet in laundry room	Incomplete
Code: ZZ_654 Category: Paint Partner: Everlast Paint	Location: Type:	Description: Outlets covered with tape in bed 3	Incomplete
Code: ZZ_655 Category: Paint Partner: Everlast Paint	Location: Type:	Description: Caulking on corner in hall by laundry	Incomplete
Code: ZZ_658 Category: Paint Partner: Everlast Paint	Location: Bedroom 1 Type:	Description: Uneven paint on wall in master where coax is located	Incomplete
Code: ZZ_662 Category: Paint Partner: Everlast Paint	Location: Type:	Description: Paint one location in master closet	Incomplete
Code: ZZ_664 Category: Paint Partner: Everlast Paint	Location: Type:	Description: Caulking missing by tile and baseboard in entry	Incomplete

All Defects	Lot 6/Tract 6260		
Code: ZZ_668 Category: Paint Partner: Everlast Paint	Location: Dining Nook Type:	Description: Paint by outlet in dining nook	Incomplete
Code: ZZ_669 Category: Paint Partner: Everlast Paint	Location: Type:	Description: Paint trim on man door	Incomplete
Fenceworks			
Code: ZZ_672 Category: Fence Partner: Fenceworks	Location: Type:	Description: Missing fence	Incomplete
G&G Concrete			
Code: ZZ_671 Category: Concrete Partner: G&G Concrete	Location: Type:	Description: Concrete chuck missing on rear garage door	Incomplete
Ohanians Drywall			
Code: ZZ_643 Category: Drywall Partner: Ohanians Drywall	Location: Kitchen Type: Crack/gash/ding	Description: Drywall line to the right of hood in kitchen	Incomplete
Code: ZZ_645 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall issues a ding and texture at garage entry	Incomplete
Code: ZZ_647 Category: Drywall Partner: Ohanians Drywall	Location: Bathroom 2 Type: Crack/gash/ding	Description: Drywall hole by data in bed 2	Incomplete

All Defects	Lot 6/Tract 6260		
Code: ZZ_653 Category: Drywall Partner: Ohanians Drywall	Location: Bedroom 3 Type: Crack/gash/ding	Description: Drywall line in bed 3 left of data pre wire	Incomplete
Code: ZZ_657 Category: Drywall Partner: Ohanians Drywall	Location: Bedroom 1 Type:	Description: Screw showing in drywall in master bedroom	Incomplete
Code: ZZ_667 Category: Drywall Partner: Ohanians Drywall	Location: Flex Super Great Room Type:	Description: Drywall crack in corner of great room	Incomplete
Quality Plumbing			
Code: ZZ_661 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 1 Type:	Description: Caulking missing by master bath tub	Incomplete
Simas Flooring & Design			
Code: ZZ_651 Category: Carpet / Hardwood / Laminate Partner: Simas Flooring & Design	Location: Type:	Description: One piece of laminate separated on landing	Incomplete
Code: ZZ_663 Category: Carpet / Hardwood / Laminate Partner: Simas Flooring & Design	Location: Type: Seam prominent/separated	Description: Separation in laminate at top of landing	Incomplete
Tile Interiors			
Code: ZZ_646 Category: Tile Partner: Tile Interiors	Location: Type:	Description: Missing transition strip in kitchen and grout	Incomplete

All Defects	Lot 6/Tract 6260		
Code: ZZ_660 Category: Tile Partner: Tile Interiors	Location: Bathroom 1 Type: Cracked tiles	Description: Chip on tile by tub in master bath	Incomplete
Code: ZZ_666 Category: Tile Partner: Tile Interiors	Location: Kitchen Type: Grout cracked/missing	Description: Grout missing on kick plate in kitchen	Incomplete
Tri Valley Plastering & Drywall			
Code: ZZ_670 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Fog splatter and uneven color on exterior of home	Incomplete
Westech			
Code: ZZ_640 Category: Electrical Partner: Westech	Location: Kitchen Type:	Description: Missing outlet on extended island	Incomplete