De Young Properties

All Defects	Lot 146/Tract 0273		
Cabinet Connection			
Code: ZZ_4381 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on fronts of doors to the right of oven. Lower cabinets	Incomplete
Code: ZZ_4383 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on right uppers to oven	Incomplete
Code: ZZ_4384 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches around fridge surround	Incomplete
Code: ZZ_4385 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on left vanity door in master bathroom	Incomplete
Code: ZZ_4386 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Finish nail holes on twe in master bath	Incomplete
California Building Products			
Code: ZZ_4390 Category: Fireplace Unit Partner: California Building Products	Location: Type:	Description: Finish start up of fireplace	Incomplete
Central Valley Rain Gutters			
Code: ZZ_4399 Category: Rain Gutters Partner: Central Valley Rain Gutters	Location: Type:	Description: Finish install of gutter downspout	Incomplete
Donald P. Dick			

All Defects	Lot 146/Tract 0273		
Code: ZZ_4397 Category: Solar Partner: Donald P. Dick	Location: Type:	Description: Finish start up of solar	Incomplete
Code: ZZ_4398 Category: HVAC Partner: Donald P. Dick	Location: Type:	Description: Finish start up of hvac	Incomplete
Elia Painting			
Code: ZZ_4378 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up needed in home	Incomplete
Ferguson			
Code: ZZ_4391 Category: Appliances Partner: Ferguson	Location: Type:	Description: Appliances missing in kitchen	Incomplete
Fresno Shower Door & Mirror			
Code: ZZ_4382 Category: Shower Door & Mirror Partner: Fresno Shower Door & Mirror	Location: Type:	Description: Missing glass in cabinets in kitchen	Incomplete
Code: ZZ_4387 Category: Shower Door & Mirror Partner: Fresno Shower Door & Mirror	Location: Type:	Description: Missing shower door in master bath shower	Incomplete
HSI			
Code: ZZ_4392 Category: Fire Sprinklers Partner: HSI	Location: Type:	Description: Finish fire sprinkler caps	Incomplete

All Defects	Lot 146/Tract 0273		
LinkUs			
Code: ZZ_4400 Category: Low Voltage Electrical Partner: LinkUs	Location: Type:	Description: Missing camera on front of home	Incomplete
Matthews Quality Construction			
Code: ZZ_4389 Category: Millwork Partner: Matthews Quality Construction	Location: Type:	Description: Baseboard damaged in master bedroom	Incomplete
Code: ZZ_4393 Category: Millwork Partner: Matthews Quality Construction	Location: Type:	Description: Damaged baseboard in bed 3	Incomplete
Ohanians Drywall			
Code: ZZ_4388 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Fill holes in drywall in master bedroom	Incomplete
Tri Valley Plastering & Drywall			
Code: ZZ_4396 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Stucco touch up front entryway	Incomplete
Visalia Tile			
Code: ZZ_4379 Category: Tile Partner: Visalia Tile	Location: Type:	Description: Grout crack on kitchen backsplash	Incomplete
Westech			

All Defects	Lot 146/Tract 0273		
Code: ZZ_4380 Category: Electrical Partner: Westech	Location: Type:	Description: Missing under cabinet lighting in kitchen	Incomplete
Code: ZZ_4394 Category: Electrical Partner: Westech	Location: Type:	Description: Missing vanity light in bath 2	Incomplete
Code: ZZ_4395 Category: Electrical Partner: Westech	Location: Type:	Description: Missing vanity lights in master bath	Incomplete