## **De Young Properties**

All Defects	Lot 128/Tra	Lot 128/Tract 0273		
Anlin Windows				
Code: ZZ_3821 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Missing screens on all windows	Incomplete	
Code: ZZ_3838  Category: Windows  Partner: Anlin Windows	Location: Type:	Description: Window in dining room won't latch	Incomplete	
Code: ZZ_3839  Category: Windows  Partner: Anlin Windows	Location: Type:	Description: Window in master bed won't latch	Incomplete	
Cabinet Connection				
Code: ZZ_3826 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Finish twe in bath 2	Incomplete	
Code: ZZ_3835  Category: Cabinets  Partner: Cabinet Connection	Location: Type:	Description: Twe missing in kitchen	Incomplete	
Code: ZZ_3844  Category: Cabinets  Partner: Cabinet Connection	Location: Type:	Description: Twe missing in master bathroom	Incomplete	
Code: ZZ_3845 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet touch up in master bath top drawer	Incomplete	
Ferguson				

All Defects	Lot 128/Tra	oct 0273	
Code: ZZ_3836  Category: Appliances  Partner: Ferguson	Location: Type:	Description: Finish install of dishwasher	Incomplete
Code: ZZ_3837  Category: Appliances  Partner: Ferguson	Location: Type:	Description: Finish install of oven	Incomplete
Fresno Shower Door & Mirror			
Code: ZZ_3842  Category: Shower Door & Mirror  Partner: Fresno Shower Door & Mirror	Location: Type:	Description: Shower enclosure missing in master bathroom	Incomplete
HSI			
Code: ZZ_3823  Category: Fire Sprinklers  Partner: HSI	Location: Type:	Description: Finish fire sprinkler cap in bed 3	Incomplete
Code: ZZ_3828  Category: Fire Sprinklers  Partner: HSI	Location: Type:	Description: Finish fire sprinkler in bed 2	Incomplete
Code: ZZ_3829  Category: Fire Sprinklers  Partner: HSI	Location: Type:	Description: Finish fire sprinkler in whole home	Incomplete
Ohanians Drywall			
Code: ZZ_3841  Category: Drywall  Partner: Ohanians Drywall	Location: Type:	Description: Drywall repair by coax in master bedroom	Incomplete
Quality Plumbing			

All Defects	Lot 128/Tract 0273		
Code: ZZ_3825  Category: Plumbing  Partner: Quality Plumbing	Location: Type:	Description: Finish tub faucet in bath 2	Incomplete
Code: ZZ_3834  Category: Plumbing  Partner: Quality Plumbing	Location: Type:	Description: Finish install of faucet in kitchen	Incomplete
Westech			
Code: ZZ_3822 Category: Electrical Partner: Westech	Location: Type:	Description: Missing light in bed 3	Incomplete
Code: ZZ_3824  Category: Electrical  Partner: Westech	Location: Type:	Description: Missing vanity light in bath 2	Incomplete
Code: ZZ_3827  Category: Electrical  Partner: Westech	Location: Type:	Description: Finish light in bed 2	Incomplete
Code: ZZ_3830  Category: Electrical  Partner: Westech	Location: Type:	Description: Light not working in hall	Incomplete
Code: ZZ_3831  Category: Electrical  Partner: Westech	Location: Type:	Description: Finish electrical in laundry room lights don't work	Incomplete
Code: ZZ_3832  Category: Electrical  Partner: Westech	Location: Type:	Description: Install faceplate on light switches in great room	Incomplete
Code: ZZ_3833  Category: Electrical  Partner: Westech	Location: Type:	Description: Lights don't work in great room or kitchen	Incomplete

All Defects	Lot 128/Tract 0273		
Code: ZZ_3840  Category: Electrical  Partner: Westech	Location: Type:	Description: Install light in master bedroom	Incomplete
Code: ZZ_3843  Category: Electrical  Partner: Westech	Location: Type:	Description: Vanity lights missing in master bath	Incomplete
Code: ZZ_3846  Category: Electrical  Partner: Westech	Location: Type:	Description: Garage lights are not installed in garage	Incomplete
Code: ZZ_3847  Category: Electrical  Partner: Westech	Location: Type:	Description: Door bell not installed	Incomplete
Code: ZZ_3848  Category: Electrical  Partner: Westech	Location: Type:	Description: Carriage lights not installed outside	Incomplete