De Young Properties

All Defects	Lot 1/Tract 6180		
Anlin Windows			
Code: ZZ_076 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Window frame on slide smudged	Incomplete
Cabinet Connection			
Code: ZZ_078 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Missing cabinet handle in laundry room	Incomplete
De Young Properties			
Code: ZZ_075 Category: Paint Partner: De Young Properties	Location: Type:	Description: Trim in bonus room	Incomplete
Code: ZZ_077 Category: Paint Partner: De Young Properties	Location: Type:	Description: Paint in bed 2 above closet	Incomplete
Tri Valley Plastering & Drywall			
Code: ZZ_079 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Fog exterior of home	Incomplete