De Young Properties

Lot 1/Tract 1812	Items: 61	CH Items: 21	Checklist Inspections: 536
Anlin Windows			
Code: ZZ_040			
Category: Windows Partner: Anlin Windows	Location: Bedroom 5 Type: Window missing a screen	Description: Missing screens in house	Complete
Code: ZZ_059			
Category: Windows Partner: Anlin Windows	Location: Bedroom 1 Type: Window frame has scratches/chips/gouges	Description: Master bedroom window has scratches on the frame	Complete
Code: ZZ_060			
Category: Windows Partner: Anlin Windows	Location: Bathroom 1 Type: Window lock is not installed and/or is not working	Description: Master bath Window above the shower doesn't lock	Complete
Cabinet Connect	ion		
Code: ZZ_041			
Category: Cabinets Partner: Cabinet	Location: Bathroom 3 Type: Adjust drawer	Description: Bath 3: side by bed 5 - cabinet drawer needs adjustment	CRITICAL Complete
Code: 77, 045			
Code: ZZ_045 Category: Cabinets	Location: Bathroom 3	Description: Bath 3 vanity by	CDITICAL
Partner: Cabinet Connection	Type: Adjust drawer	bed 4 door needs to be adjusted or false front to bed aligned	CRITICAL Complete
Code: ZZ_050			
Category: Cabinets	Location: Bathroom 2	Description: bath 2 cabinets: some stains on faces of false	Complete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets	front and doors, chip on false front	complete.

Lot 1/Tract 1812	Items: 61	CH Items: 21	Checklist Inspections: 536
Code: ZZ_063			
Category: Cabinets	Location: Bathroom 1	Description: Master bath cabinets by closet need touch	Complete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets	on top of drawer, check drawers for alignment	Complete
Code: ZZ_064		Description: Master bath	
Category: Cabinets	Location: Bathroom 1	cabinets: vanity by bedroom - right side drawers check	Complete
Partner: Cabinet Connection	Type: Scratches/chips/cracks/gouges in cabinets	adjustment and top drawer has some scratches and needs touch up	Complete
Code: ZZ_076			
Category: Cabinets	Location: Bathroom 5	Description: Bath 5 cabinet drawers need to be adjusted	CRITICAL
Partner: Cabinet Connection	Type: Adjustment	and inside the cabinet there's a stain on bottom right side	Complete
Code: ZZ_081		December Wheles a calcinote	
Category: Cabinets	Location: Kitchen	Description: Kitchen cabinets fridge surround: nail holes	Complete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	inside of panel next to fridge, chips and scratches on surround, and on crown	Complete
Code: ZZ_083		Description: Tall cabinet by	
- Category: Cabinets	Location: Kitchen	laundry: inside there's scratches on the doors and	
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	shelf needs to be swapped out to one worth out excessive chipping, long cabinet doors need to be connected.	Complete
Code: ZZ_084			
Category: Cabinets	Location: Kitchen	Description: Cabinets left of	Complete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	stove inside the upper scratch on door	Complete
Code: ZZ_085			
Category: Cabinets	Location: Kitchen	Description: Cabinets right of stove - upper has scratch	Carrel
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	inside the door, top of drawer needs touch up	Complete

Lot 1/Tract 1812	Items: 61	CH Items: 21	Checklist Inspections: 536
Code: ZZ_086		Description: Oven frame: side	
Category: Cabinets	Location: Kitchen	Description: Oven frame: side has some scratches and chips, side has chip at bottom - lots of chips and scratches	Complete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks		
Code: ZZ_087			
Category: Cabinets	Location: Kitchen	Description: Sides of island	Complete
Partner: Cabinet Connection	Type: Cabinets have scratches, chips, and/or cracks	have some stains	Complete
Central Valley Ra	ain Gutters		
Code: ZZ_092			
Category: Rain Gutters	Location: Backyard	Description: Gutter down spout by patio - there's a	Complete
Partner: Central Valley Rain Gutters	Type: Not connected to drain system	drain but no down spout	Complete
Code: ZZ_093			
Category: Rain Gutters	Location: Backyard	Description: Other gutter	Complete
Partner: Central Valley Rain Gutters	Type: Not connected to drain system	downspout spout is not connected to drain by patio	
Code: ZZ_097			
Category: Rain Gutters	Location: Backyard	Description: Gutter down	Complete
Partner: Central Valley Rain Gutters	Type: Not connected to drain system	spout missing in side yard	
Elia Painting			
Code: ZZ_038		Description D. 15	
Category: Paint	Location: Bedroom 5	Description: Bed 5 paint touch up on door trim inside and out, inside of door, inside	Complete
Partner: Elia Painting	Type: Touch-up required	the closet up at ceiling	

	Checklist Inspections: 536
ription: Paint touch up ed in bath 3, doors and trim, bullnose, above er area	Complete
ription: Bed 4 paint nup needed inside the t, clean off paint from t door hinges	Complete
ription: Bed 3 closet s paint touch up - corner like it wasn't painted door trim as well and of millwork	Complete
ription: Caulking under trim	Complete
ription: Bed 2 paint nup needed - closet door clean off paint from hinges, closet door es clean off paint	Complete
ription: Paint touch up ed in master water t door trim	Complete
ription: Paint touch up ed inside the master t - millwork and door	Complete
ription: Paint touch up ed inside the powder door trim and base	Complete
e	d inside the powder

Lot 1/Tract 1812	Items: 61	CH Items: 21	Checklist Inspections: 536
Code: ZZ_069 Category: Solid Surface Partner: Granite Mountain Stone Design	Location: Bathroom 1 Type: Stain on counter	Description: Master bath vanity counter has some stains	CRITICAL Complete
Ideal Custom Til	e		
Code: ZZ_042 Category: Tile Partner: Ideal Custom Tile	Location: Bathroom 3 Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Bath 3 tile: Crack at grout line under vanity bed bed 5, pencil marks on tile in shower and toilet area, grout touch up needed under vanity by bed 4	Complete
Code: ZZ_051 Category: Tile Partner: Ideal Custom Tile	Location: Bathroom 2 Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Bath 2 tile touch up needed: thin set on tile, grout cracks by shower, lots of pencil marks, fill in grout under door trim	Complete
Code: ZZ_062 Category: Tile Partner: Ideal Custom Tile	Location: Bathroom 1 Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Tile in shower - bullnose tile at entry missing, top corner piece missing, some chipped tiles, some grout touch up needed. Grout touch up needed next to tub	Complete
Code: ZZ_078 Category: Tile Partner: Ideal Custom Tile	Location: Entryway Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Some grout touch up needed at base of stair banister and inside the storage closet under the stairs	Complete
Code: ZZ_079 Category: Tile Partner: Ideal Custom Tile	Location: Flex Den Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Tile by base by flex den missing grout or caulk	Complete
Code: ZZ_082 Category: Tile Partner: Ideal Custom Tile	Location: Kitchen Type: Tile missing	Description: Tile missing next to foot of fridge surround cabinet	CRITICAL Complete

Checklist Lot 1/Tract 1812 Items: 61 CH Items: 21 **Inspections:** 536 Code: ZZ_090 Description: Tile next to Location: Laundry Room laundry sink has a big gap -Category: Tile CRITICAL either needs more tile or Complete Type: Gap at tile to base Partner: Ideal arout Custom Tile John Rocha Code: ZZ 049 Description: Remove excess roof tile from second roof Location: Bedroom 3 Category: Paint CRITICAL outside of bed 3 Check roof Complete Type: Clean off roof for any cracked or missing Partner: John tile and remove any debris Rocha John Ventresca Co Code: ZZ_077 Category: Location: Great Room Description: Fireplace Fireplace Surround surround has some grout Complete Type: Mortar has cracks or is missing cracks and stains in areas Partner: John Ventresca Co Landscape Connection Code: ZZ 095 Category: Location: Backyard Description: Gutter Landscaping CRITICAL downspout by man - door is Type: Man door gutter downspout not Complete not connected to drain vent connected to drain Partner: Landscape Connection MV Style Electric Code: ZZ 057 Description: Bed 2 light Category: Location: Bedroom 2 switch wired wrong - switch CRITICAL Electrical doesn't turn light off and on -Complete Type: Electrical switch wired wrong the dimmer switch does Partner: MV Style Electric Code: ZZ_072 Location: Entryway Category: Description: Front door and Electrical porch exterior lights not Complete Type: Electrical outlets missing or not working functional Partner: MV Style Electric

Checklist Lot 1/Tract 1812 Items: 61 CH Items: 21 **Inspections:** 536 Code: ZZ_073 Description: Powder bath Category: Location: Bathroom 5 CRITICAL Electrical light is not centered with Complete Type: Light needs to be moved over sink Partner: MV Style Electric Code: ZZ 075 Category: Location: Bathroom 5 Description: Bath 5 - light is CRITICAL Electrical not centered with sink Complete Type: Light needs to be moved over Partner: MV Style Electric Code: ZZ 080 Description: Can lights and Location: Dining Room Category: pre-wire are wired wrong in CRITICAL Electrical dining area - cans are on Type: Wiring done wrong in dining Complete recessed switch, need to area Partner: MV Style swap wires Electric Code: ZZ_088 Location: Kitchen Category: Description: Finish hood Electrical Complete Type: Electrical outlets missing or not wiring functional Partner: MV Style Electric Matthews Quality Construction Code: ZZ_056 Category: Millwork Location: Bedroom 2 Description: Bed 2 closet CRITICAL door left - crack inside Complete Type: Closet door crack Partner: Matthews Quality Construction Code: ZZ_058 Category: Millwork Location: Bedroom 1 Description: Master bedroom: CRITICAL baseboards by bathroom Complete Type: Lines in baseboards have lines Partner: Matthews Quality Construction

Lot 1/Tract 1812	Items: 61	CH Items: 21	Checklist Inspections: 536
Code: ZZ_071 Category: Drywall Partner: Ohanians Drywall	Location: Entryway Type: Drywall has crack, gash, hole, and/or gouge	Description: Drywall touch up inside entry coat closet just by antenna pre-wire and next to outlet by powder bath	Complete
Code: ZZ_089 Category: Drywall Partner: Ohanians Drywall	Location: Laundry Room Type: Drywall has tape line and/or compression line	Description: Drywall line inside the laundry room on the first floor	CRITICAL Complete
Code: ZZ_091 Category: Drywall Partner: Ohanians Drywall	Location: Laundry Room Type: Nail pop and home	Description: Drywall nail pop and hole by switch in laundry room	CRITICAL Complete
Quality Plumbin	g		
Code: ZZ_052 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 2 Type: Missing faucet, shower head, handle, etc	Description: Install drain cover	CRITICAL Complete
Code: ZZ_061 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 1 Type: Caulking at tub	Description: Caulking around the tub needs touch up	CRITICAL Complete
Tri Valley Plaste	ering & Drywall		
Code: ZZ_094 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Backyard Type: Stucco over the drain needs to be removed	Description: Remove stucco from bathroom drain clean out	CRITICAL Complete
Code: ZZ_096 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Stucco crack by back window - stucco touch up needed around home and at thresholds	Complete

Checklist Lot 1/Tract 1812 Items: 61 CH Items: 21 Inspections: **536** Code: ZZ_098 Description: Stucco touch up needed in courtyard by slider Category: Stucco Location: Courtyard Complete large cracks, threshold and Partner: Tri Valley Type: Chip/crack/gouge lots of touch up needed Plastering & Drywall