De Young Properties

All Defects	Lot 37/Trac	Lot 37/Tract 6164		
Anlin Windows				
Code: ZZ_1795 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Window in great room won't latch	Incomplete	
Cabinet Connection				
Code: ZZ_1780 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Adjust door under cooktop in kitchen	Incomplete	
Code: ZZ_1781 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Missing handle in kitchen	Incomplete	
Code: ZZ_1782 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Drawers in kitchen are not aligned	Incomplete	
Code: ZZ_1783 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Chip on oven surround in kitchen	Incomplete	
Code: ZZ_1792 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches in multigen cabinets	Incomplete	
Code: ZZ_1794 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Missing bobs in multigen bath	Incomplete	
Code: ZZ_1797 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Adjust drawers in bath 3 hard to open	Incomplete	

All Defects	Lot 37/Trac	Lot 37/Tract 6164		
Code: ZZ_1802 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches in bath 2	Incomplete	
Code: ZZ_1803 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Install false front in bath 2	Incomplete	
De Young Properties				
Code: ZZ_1807 Category: Builder Personnel Partner: De Young Properties	Location: Type:	Description: Turn on water main	Incomplete	
Diebert Tile				
Code: ZZ_1785 Category: Tile Partner: Diebert Tile	Location: Type:	Description: Grout crack backsplash	Incomplete	
Code: ZZ_1786 Category: Tile Partner: Diebert Tile	Location: Type:	Description: Wrong color grout on kitchen backsplash	Incomplete	
Code: ZZ_1788 Category: Tile Partner: Diebert Tile	Location: Type:	Description: Large area of of miss aligned tile	Incomplete	
Code: ZZ_1800 Category: Tile Partner: Diebert Tile	Location: Type:	Description: Tile not complete in master bath by tub	Incomplete	
Donald P. Dick				
Code: ZZ_1787 Category: HVAC Partner: Donald P. Dick	Location: Type:	Description: Un finished flute in kitchen	Incomplete	

All Defects	Lot 37/Tract 6164		
Elia Painting			
Code: ZZ_1799 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint in start	Incomplete
Code: ZZ_1801 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint drips on base in bed 2	Incomplete
Code: ZZ_1805 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint patches in bed 3	Incomplete
Ferguson			
Code: ZZ_1784 Category: Appliances Partner: Ferguson	Location: Type:	Description: Missing microwave	Incomplete
Code: ZZ_1790 Category: Appliances Partner: Ferguson	Location: Type:	Description: Dishwasher not hooked up	Incomplete
Code: ZZ_1793 Category: Appliances Partner: Ferguson	Location: Type:	Description: Missing microwave in multigen	Incomplete
Granite Mountain Stone Design			
Code: ZZ_1796 Category: Solid Surface Partner: Granite Mountain Stone Design	Location: Type:	Description: Missing counter top in laundry room	Incomplete
Ohanians Drywall			

All Defects	Lot 37/Trac	Lot 37/Tract 6164		
Code: ZZ_1791 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Booger on drywall in dining nook	Incomplete	
Code: ZZ_1804 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Patch holes in bed 3	Incomplete	
Quality Plumbing				
Code: ZZ_1789 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Missing airrater tool	Incomplete	
Tri Valley Plastering & Drywall				
Code: ZZ_1806 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Stucco you ch up in back of home	Incomplete	
True Frame				
Code: ZZ_1798 Category: Framing Partner: True Frame	Location: Type:	Description: Now in wall in entry	Incomplete	