De Young Properties

All Defects	Lot 20/Tract 6260		
Anlin Windows			
Code: ZZ_1153 Category: Windows Partner: Anlin Windows	Location: Type: Window operation	Description: Slide and glide all windows and sliders throughout home	Incomplete
Code: ZZ_1168 Category: Windows Partner: Anlin Windows	Location: Courtyard Type: Window operation	Description: Large slider from hall to courtyard missing screens and the back trim is coming off on the left side door	Incomplete
Code: ZZ_1178 Category: Windows Partner: Anlin Windows	Location: Dining Nook Type: Window operation	Description: Dining nook missing screen at window	Incomplete
Code: ZZ_1180 Category: Windows Partner: Anlin Windows	Location: Dining Nook Type: Window frame scratched/chipped/dented	Description: Lock at dining nook window has some scratches	Incomplete
Code: ZZ_1199 Category: Windows Partner: Anlin Windows	Location: Courtyard Type: Window operation	Description: Slider track at large slider from dining to courtyard is rippled - needs to be replaced	Incomplete
Cabinet Connection	ו		
Code: ZZ_1158 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Dent(s), ding(s), scratch(es)	Description: Cabinets in bath 2 need touch up in several places inside and out Also missing trim piece under counter Please check inside all cabinets for tape	Incomplete

All Defects	Lot 20/Tract 6260		
Code: ZZ_1161 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Dent(s), ding(s), scratch(es)	Description: Upper cabinets in laundry room need touch up in several places inside and outside - check inside and crown for tape	Incomplete
Code: ZZ_1162 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Part missing	Description: Toe kick under laundry lower cabinet under sink missing Also trim at base of side of lower cabinet missing	Incomplete
Code: ZZ_1164 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Dent(s), ding(s), scratch(es)	Description: Lower cabinet under the laundry sink needs touch up in several places inside and out	Incomplete
Code: ZZ_1169 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Long cabinet on left side of fridge surround - crown installed is upside down Inside upper and lower installation is not complete - shelves not installed and doors not connected Several chips and scratches inside	Incomplete
Code: ZZ_1170 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Fridge surround has some chips and scratches Check inside the upper above the fridge too	Incomplete
Code: ZZ_1171 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Cabinet to the right of the fridge needs touch up - has chips and scratches on doors and inside and shelves Also corner cabinets	Incomplete
Code: ZZ_1172 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Part missing	Description: Drawers under cooktop missing hardware	Incomplete
Code: ZZ_1173 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Cabinets on either side of the hood need touch up inside and out Check inside all cabinets for tape Both uppers and lowers	Incomplete

All Defects	Lot 20/Tract 6260		
Code: ZZ_1174 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Oven frame needs touch up inside the cabinet above the microwave and the drawer under the oven needs touch up and to be adjusted	Incomplete
Code: ZZ_1175 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Trim under kitchen sink missing Cabinet under the sink also needs touch up inside	Incomplete
Code: ZZ_1176 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Part missing	Description: Missing toe kick under the kitchen sinks and island	Incomplete
Code: ZZ_1177 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Part missing	Description: Missing perimeter trim around the kitchen and quarter round at island side	Incomplete
Code: ZZ_1182 Category: Cabinets Partner: Cabinet Connection	Location: Great Room Type: Part missing	Description: Missing trim piece at cabinet base in great room	Incomplete
Code: ZZ_1192 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Dent(s), ding(s), scratch(es)	Description: Master bath right side vanity needs touch up in several places - check inside drawers for tape	Incomplete
Code: ZZ_1193 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Adjust door(s)	Description: Center cabinet vanity right side upper door needs adjustment Trim needs touch up too lower door needs adjustment too	Incomplete
Code: ZZ_1194 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Dent(s), ding(s), scratch(es)	Description: Left side vanity needs touch up in several places	Incomplete

All Defects	Lot 20/Tract 6260			
Citadel Roofing and Solar				
Code: ZZ_1211 Category: Roofing Partner: Citadel Roofing and Solar	Location: Exterior Type: Cracked/broken/chipped roof tile(s)	Description: Check roof for cracked roof tiles and also clean off any debris	Incomplete	
Code: ZZ_1211 Category: Roofing Partner: Citadel Roofing and Solar	Location: Exterior Type:	Description: Check roof for cracked roof tiles and also clean off any debris	Incomplete	
Donald P. Dick				
Code: ZZ_1206 Category: HVAC Partner: Donald P. Dick	Location: Great Room Type: A/C not cooling	Description: HVAC system doesn't seem to be working	Incomplete	
Everlast Paint				
Code: ZZ_1151 Category: Paint Partner: Everlast Paint	Location: Bedroom 2 Type: Cleanup	Description: Paint touch up needed in several places around bedroom 2 including inside the closet and closet doors, around windows and on walls	Incomplete	
Code: ZZ_1154 Category: Paint Partner: Everlast Paint	Location: Entryway Type: Cleanup	Description: Paint touch up needed around the entryway walls - look up and down And on interior side of front door	Incomplete	
Code: ZZ_1155 Category: Paint Partner: Everlast Paint	Location: Bedroom 3 Type: Cleanup	Description: Paint touch-up needed in several places around bedroom 3 including around the window and inside of the closet Check door trim areas too inside and out	Incomplete	
Code: ZZ_1157 Category: Paint Partner: Everlast Paint	Location: Entryway Type: Cleanup	Description: Paint and door trim caulking grout touch up needed in several places in hall area - check around doors for bed 2, bed 3, laundry room, and bath 2	Incomplete	

All Defects	Lot 20/Tract 6260		
Code: ZZ_1159 Category: Paint Partner: Everlast Paint	Location: Bathroom 2 Type: Cleanup	Description: Paint touch up needed around bath 2 including above the shower around the window area needs clean up Missing caulking at door trim	Incomplete
Code: ZZ_1163 Category: Paint Partner: Everlast Paint	Location: Laundry Room Type: Cleanup	Description: Paint touch up needed in several places around the laundry room	Incomplete
Code: ZZ_1165 Category: Paint Partner: Everlast Paint	Location: Laundry Room Type: Cleanup	Description: Paint touch up needed around laundry room in several places including inside the coat closet	Incomplete
Code: ZZ_1167 Category: Paint Partner: Everlast Paint	Location: Dining Room Type: Cleanup	Description: Paint touch up needed around the dining room in several places including around windows	Incomplete
Code: ZZ_1179 Category: Paint Partner: Everlast Paint	Location: Dining Nook Type: Cleanup	Description: Paint touch up needed around the dining nook	Incomplete
Code: ZZ_1183 Category: Paint Partner: Everlast Paint	Location: Great Room Type: Cleanup	Description: Paint touch up needed in several places around the great room	Incomplete
Code: ZZ_1184 Category: Paint Partner: Everlast Paint	Location: Den Type: Cleanup	Description: Paint touch up needed in den in several places	Incomplete
Code: ZZ_1195 Category: Paint Partner: Everlast Paint	Location: Bathroom 1 Type: Cleanup	Description: Paint touch up needed in several places around the master bath and master closet	Incomplete

All Defects	Lot 20/Tract 6260		
Code: ZZ_1196 Category: Paint Partner: Everlast Paint	Location: Bedroom 1 Type: Cleanup	Description: Paint touch up needed in several places around master bedroom	Incomplet
Code: ZZ_1203 Category: Paint Partner: Everlast Paint	Location: Garage Type: Cleanup	Description: Paint touch up needed on side garage door - was closed too soon and paint tuck together where white meets the grey Needs touch up	Incomplet
Fenceworks Code: ZZ_1202 Category: Fence Partner: Fenceworks	Location: Exterior Type: Gate string missing/broken	Description: Missing side yard fence and gate	Incomplet
G&G Concrete Code: ZZ_1205 Category: Concrete Partner: G&G Concrete	Location: Backyard Type:	Description: Form boards for concrete slap for HVAC unit still in place - need to be temoved	Incomplet
John Ventresca Co Code: ZZ_1198 Category: Fireplace Surround Partner: John Ventresca Co	Location: Courtyard Type: Mortar cracked/missing	Description: Mortar cracks around the stone fireplace in several places in courtyard	Incomplet
LinkUs Code: ZZ_1166 Category: Low Voltage Electrical Partner: LinkUs	Location: Laundry Room Type:	Description: Missing plate cover for antenna pre-wire inside the coat closet	Incomplet

All Defects	Lot 20/Tract 6260		
Code: ZZ_1181 Category: Low Voltage Electrical Partner: LinkUs	Location: Great Room Type:	Description: Finish tv wiring install inside the cabinet in great room	Incomplete
Code: ZZ_1208 Category: Low Voltage Electrical Partner: LinkUs	Location: Exterior Type:	Description: Exterior cameras at front and back And Alexa speaker solutions not installed yet	Incomplete
Code: ZZ_1209 Category: Low Voltage Electrical Partner: LinkUs	Location: Great Room Type:	Description: There's a blank plate where there should be a camera in the great room	Incomplete
Code: ZZ_1210 Category: Low Voltage Electrical Partner: LinkUs	Location: Entryway Type:	Description: Missing audiophile residence And smart lock should be in front door but it's not there yet	Incomplete
Matthews Quality C	Construction		
Code: ZZ_1186 Category: Millwork Partner: Matthews Quality Construction	Location: Bedroom 1 Type:	Description: Door from master to patio needs to be adjusted Difficult to turn lock - seems out of alignment	Incomplete
Ohanians Drywall			
Code: ZZ_1160 Category: Drywall Partner: Ohanians Drywall	Location: Bathroom 2 Type: Crack/gash/ding	Description: Sensor wire at window has gap around it - need to be filled in more	Incomplete
Code: ZZ_1185 Category: Drywall Partner: Ohanians Drywall	Location: Den Type: Crack/gash/ding	Description: Gap at window sensor wiring base in den	Incomplete
Quality Plumbing			

All Defects	Lot 20/Tract 6260		
Code: ZZ_1188 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 2 Type:	Description: Drain cover missing in bath 2 shower	Incomplete
Code: ZZ_1189 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 1 Type:	Description: Drain cover missing in master shower	Incomplete
Code: ZZ_1207 Category: Plumbing Partner: Quality Plumbing	Location: Laundry Room Type:	Description: Laundry room faucet is incorrect	Incomplete
Simas Flooring & D	esign		
Code: ZZ_1152 Category: Carpet / Hardwood / Laminate Partner: Simas Flooring & Design	Location: Bedroom 2 Type: Wood or vinyl damage: gouge/tear/scuff	Description: Laminate tile cut too short under window in bedroom 2	Incomplete
Code: ZZ_1156 Category: Carpet / Hardwood / Laminate Partner: Simas Flooring & Design	Location: Bedroom 3 Type:	Description: Cut or mark in laminate tile next to closet in bed 3	Incomplete
Tile Interiors			
Code: ZZ_1187 Category: Tile Partner: Tile Interiors	Location: Bathroom 1 Type: Grout cracked/missing	Description: Tile touch up needed around master shower including the grout at the base and missing corner piece	Incomplete

All Defects	Lot 20/Tract 6260		
Code: ZZ_1190 Category: Tile Partner: Tile Interiors	Location: Bathroom 1 Type: Grout cracked/missing	Description: Finish installing tile toe kick under the vanities in master	Incomplete
Code: ZZ_1191 Category: Tile Partner: Tile Interiors	Location: Bathroom 1 Type: Tile(s) not flush	Description: 1 tile by master vanity is raised - doesn't pass credit card test Please level that tile	Incomplete
Tri Valley Plastering	g & Drywall		
Code: ZZ_1197 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Courtyard Type: Chipped/gouged stucco	Description: Stucco touch up needed around the footings in the courtyard	Incomplete
Code: ZZ_1200 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chipped/gouged stucco	Description: Stucco touch up needed around doorbell - there's a large gap that needs to be filled in	Incomplete
Code: ZZ_1201 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chipped/gouged stucco	Description: Stucco touch up needed next to front door and window area	Incomplete
Code: ZZ_1204 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Backyard Type: Chipped/gouged stucco	Description: Stucco touch up needed in several places around the covered patio Including under thresholds	Incomplete