De Young Properties

Lot 1/Tract 1812	Items: 5	CH Items: 2	Checklist Inspections: 0
Central Valley Rain Gutters			
Code: ZZ_092 Category: Rain Gutters Partner: Central Valley Rain Gutters	Location: Backyard Type: Not connected to drain system	Description: Gutter down spout by patio - there's a drain but no down spout	Complete
Code: ZZ_093 Category: Rain Gutters Partner: Central Valley Rain Gutters	Location: Backyard Type: Not connected to drain system	Description: Other gutter downspout spout is not connected to drain by patio	Complete
Code: ZZ_097 Category: Rain Gutters Partner: Central Valley Rain Gutters	Location: Backyard Type: Not connected to drain system	Description: Gutter down spout missing in side yard	Complete
Landscape Connection			
Code: ZZ_095 Category: Landscaping Partner: Landscape Connection	Location: Backyard Type: Man door gutter downspout not connected to drain	Description: Gutter downspout by man - door is not connected to drain vent	CRITICAL Complete
Tri Valley Plastering & Drywall			
Code: ZZ_094 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Backyard Type: Stucco over the drain needs to be removed	Description: Remove stucco from bathroom drain clean out	CRITICAL Complete