De Young Properties

All Defects	Lot 13/Tract 6102		
Cabinet Connection			
Code: ZZ_115 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Drop zone cabinet lower has mark on corner Several kitchen drawers have missing hardware Kitchen drawer below oven needs to be fixxed	Incomplete
Code: ZZ_117 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Part missing	Description: Gap in kitchen cabinet next to drop zone	Incomplete
Code: ZZ_119 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Holes in cabinet Missing caulking Overspray on cabinet	Incomplete
California Building Pro	ducts		
Code: ZZ_114 Category: Fireplace Unit Partner: California Building Products	Location: Great Room Type:	Description: Fireplace insert bottom front piece is falling off	Incomplete
Everlast Paint			
Code: ZZ_118 Category: Paint Partner: Everlast Paint	Location: Flex Bedroom Type: Chip/gouge/scratch	Description: Chips in doors at guest suite and front coat closet and downstairs bedroom	Incomplete
Code: ZZ_120 Category: Paint Partner: Everlast Paint	Location: Laundry Room Type: Chip/gouge/scratch	Description: Laundry door frame Doors upstairs marked where touch up needed	Incomplete
HSI			

All Defects	Lot 13/Tract 6102				
Code: ZZ_113 Category: Fire Sprinklers Partner: HSI	Location: Kitchen Type:	Description: Missing fire sprinkler heads in kitchen and dining room	Incomplete		
LinkUs					
Code: ZZ_121 Category: Low Voltage Electrical Partner: LinkUs	Location: Great Room Type:	Description: LinkUs installation of tv mount missing	Incomplete		
Tri Valley Plastering & Drywall					
Code: ZZ_116	Location: Backyard	Description: Several holes in stucco at			
Category: Stucco Partner: Tri Valley Plastering & Drywall	Type: Chipped/gouged stucco	rear of house And missing stucco under sliding glass door	Incomplete		