De Young Properties

All Defects	Lot 1/Tract 6260		
Anlin Windows			
Code: ZZ_268 Category: Windows Partner: Anlin Windows	Location: Type:	Description: 2 screens torn in great room One screen missing by courtyard	Incomplete
Code: ZZ_272 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Bed 3 window latch doesn't work	Incomplete
Cabinet Connection			
Code: ZZ_267 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Touch up in kitchen trim and a few nail holes on shelves right of stove	Incomplete
California Building Products			
Code: ZZ_278 Category: Fireplace Unit Partner: California Building Products	Location: Type:	Description: Fireplace won't light	Incomplete
John Ventresca Co			
Code: ZZ_269 Category: Fireplace Surround Partner: John Ventresca Co	Location: Type:	Description: Grout cracks on fireplace surround	Incomplete
Ohanians Drywall			
Code: ZZ_271 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Bullnose upstairs	Incomplete

All Defects	Lot 1/Tract	Lot 1/Tract 6260		
Code: ZZ_276 Category: Plumbing Partner: Quality Plumbing	Location: Type:	Description: Hot water backwards on laundry sink	Incomplete	
Simas Flooring & Design				
Code: ZZ_270 Category: Carpet / Hardwood / Laminate Partner: Simas Flooring & Design	Location: Type:	Description: Short laminate in dining room	Incomplete	
Tile Interiors				
Code: ZZ_273 Category: Tile Partner: Tile Interiors	Location: Type:	Description: Tile kick missing in master bath	Incomplete	
Code: ZZ_274 Category: Tile Partner: Tile Interiors	Location: Type:	Description: Tile kick missing in bath 2	Incomplete	
Code: ZZ_275 Category: Tile Partner: Tile Interiors	Location: Type:	Description: Tile kick missing in laundry	Incomplete	
Code: ZZ_277 Category: Tile Interiors	Location: Type:	Description: Tile kick missing bath 3	Incomplete	

Partner: Tile Interiors