De Young Properties

All Defects	Lot 154/Tra	Lot 154/Tract 0273			
Anlin Windows					
Code: ZZ_4045 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Missing screens in whole home	Incomplete		
Cabinet Connection					
Code: ZZ_4046 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Missing twe in bath 2	Incomplete		
Code: ZZ_4047 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Please address scratches on cabinet door faces in bath 2	Incomplete		
Code: ZZ_4049 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Missing twe in kitchen	Incomplete		
Code: ZZ_4050 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Touch up around fridge surround and above fridge surround for scratches	Incomplete		
Code: ZZ_4051 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches on lower cabinets left of oven	Incomplete		
Code: ZZ_4052 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on fronts of doors on upper cabinet left of microwave	Incomplete		
Code: ZZ_4053 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches on fronts of cabinet on island and blemishes	Incomplete		

All Defects	Lot 154/Tra	Lot 154/Tract 0273		
Code: ZZ_4054 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scratches on doors and drawers on lower cabinets right of oven	Incomplete	
Code: ZZ_4055 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet stain is thin on the corners of the upper right doors in kitchen	Incomplete	
Code: ZZ_4060 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Missing twe in master bath cabinets	Incomplete	
Code: ZZ_4061 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches and stain removing on faces of cabinets in master bathroom	Incomplete	
Code: ZZ_4063 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Finish shut off for solar	Incomplete	
Central Valley Overhead Door				
Code: ZZ_4048 Category: Garage Door Partner: Central Valley Overhead Door	Location: Type:	Description: Garage door opener's are on site	Incomplete	
De Young Properties				
Code: ZZ_4065 Category: Builder Personnel Partner: De Young Properties	Location: Type:	Description: Complete water box front of home	Incomplete	
Ferguson				

All Defects	Lot 154/Tra	Lot 154/Tract 0273		
Code: ZZ_4057 Category: Appliances Partner: Ferguson	Location: Type:	Description: Missing all appliances	Incomplete	
Fresno Shower Door & Mirror				
Code: ZZ_4059 Category: Shower Door & Mirror Partner: Fresno Shower Door & Mirror	Location: Type:	Description: Missing shower enclosure in master bath	Incomplete	
Tri Valley Plastering & Drywall				
Code: ZZ_4062 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Repair stucco by doorbell	Incomplete	
Code: ZZ_4064 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Fill small area of stucco by window on left side of home	Incomplete	
Westech				
Code: ZZ_4056 Category: Electrical Partner: Westech	Location: Type:	Description: Missing vanity light in bath 2	Incomplete	
Code: ZZ_4058 Category: Electrical Partner: Westech	Location: Type:	Description: Missing vanity lights in master bath	Incomplete	