## **De Young Properties**

All Defects	Lot 31/Trac	Lot 31/Tract 6260		
Cabinet Connection				
Code: ZZ_526  Category: Cabinets  Partner: Cabinet Connection	Location: Type:	Description: Crooked cabinet face in kitchen	Incomplete	
Code: ZZ_531  Category: Cabinets  Partner: Cabinet Connection	Location: Type:	Description: Knick on cabinet face in bath 3	Incomplete	
Everlast Paint				
Code: ZZ_527  Category: Paint  Partner: Everlast Paint	Location: Type:	Description: Baseboard in gray room needs paint	Incomplete	
Code: ZZ_528  Category: Paint  Partner: Everlast Paint	Location: Type:	Description: Caulking on baseboard in dining room	Incomplete	
Code: ZZ_529  Category: Paint  Partner: Everlast Paint	Location: Type:	Description: Paint cut line in bonus room	Incomplete	
Code: ZZ_532  Category: Paint  Partner: Everlast Paint	Location: Type:	Description: Overspray of pain in bath 3 behind toilet	Incomplete	
Code: ZZ_535  Category: Paint  Partner: Everlast Paint	Location: Type:	Description: Baseboard in master closet 2 locations need paint	Incomplete	
Code: ZZ_536  Category: Paint  Partner: Everlast Paint	Location: Type:	Description: Caulk behind tub in master bath	Incomplete	

All Defects	Lot 31/Tract 6260		
Code: ZZ_537  Category: Paint  Partner: Everlast Paint	Location: Type:	Description: Paint in stairwell by baseboard	Incomplete
Tile Interiors			
Code: ZZ_530  Category: Tile  Partner: Tile Interiors	Location: Type:	Description: Replace cracked tiles in kitchen by slider	Incomplete
Code: ZZ_533  Category: Tile  Partner: Tile Interiors	Location: Type:	Description: Grout by tub in bath 2	Incomplete
Code: ZZ_534  Category: Tile  Partner: Tile Interiors	Location: Type:	Description: Tile corners in master shower	Incomplete
Tri Valley Plastering & Drywall			
Code: ZZ_538  Category: Stucco  Partner: Tri Valley Plastering & Drywall	Location: Type:	Description: Stucco corners of pop outs	Incomplete