De Young Properties

All Defects	Lot 34/Trac	t 6164	
Anlin Windows			
Code: ZZ_1341 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Missing window latch in master bedroom	Incomplete
Cabinet Connection			
Code: ZZ_1335 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Install scribe on sides of island	Incomplete
Code: ZZ_1344 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Adjust handle in master bath	Incomplete
Elia Painting			
Code: ZZ_1331 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up in bed 6	Incomplete
Code: ZZ_1333 Category: Paint Partner: Elia Painting	Location: Type:	Description: Clean paint off tile by stairs	Incomplete
Code: ZZ_1337 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint base in laundry room	Incomplete
Code: ZZ_1338 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint touch up in stairwell	Incomplete

All Defects	Lot 34/Trac	Lot 34/Tract 6164		
Code: ZZ_1339 Category: Paint Partner: Elia Painting	Location: Type:	Description: Paint trim upstairs	Incomplete	
Ideal Custom Tile				
Code: ZZ_1330 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Caulk bottom of door casings where there is tile	Incomplete	
Code: ZZ_1332 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Grout tile tow kick in bath 4	Incomplete	
Code: ZZ_1334 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Grout crack on tile by island	Incomplete	
Code: ZZ_1336 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Grout tile backsplash in kitchen by outlet	Incomplete	
Code: ZZ_1340 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Tile edge in shower	Incomplete	
Code: ZZ_1342 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Missing grout in master bath shower	Incomplete	
Code: ZZ_1343 Category: Tile Partner: Ideal Custom Tile	Location: Type:	Description: Missing screw in master shower drain	Incomplete	
Tri Valley Plastering & Drywall				

All Defects Lot 34/Tract 6164 Code: ZZ_1345 Location: Description: Stucco by front door by weep screed chipped off Category: Stucco Incomplete Type:

Partner: Tri Valley Plastering &

Drywall