De Young Properties

All Defects	Lot 144/Tract 0273		
Anlin Windows			
Code: ZZ_2423 Category: Windows Partner: Anlin Windows	Location: Bathroom 3 Type: Window operation	Description: Bath 3 missing screen at window	Incomplete
Code: ZZ_2426 Category: Windows Partner: Anlin Windows	Location: Bedroom 4 Type: Window operation	Description: Bed 4 missing screen at window	Incomplete
Code: ZZ_2426 Category: Windows Partner: Anlin Windows	Location: Bedroom 3 Type: Window operation	Description: Bed 3 missing screen at window	Incomplete
Code: ZZ_2432 Category: Windows Partner: Anlin Windows	Location: Bathroom 2 Type: Window operation	Description: Bath 2: missing screen at window	Incomplete
Code: ZZ_2441 Category: Windows Partner: Anlin Windows	Location: Dining Nook Type: Window operation	Description: Check slider door Screen hard to open and close	Incomplete
Cabinet Connection			
Code: ZZ_2421 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 3 Type: Dent(s), ding(s), scratch(es)	Description: Bath 3: vanity top left and top right side drawers need to be adjusted Center support trim under sink inside cabinet needs to be replaced - cut too deep Back panel under sink has some cuts Trim under sink needs touch up Few scratches	Incomplete

All Defects	Lot 144/Tract 0273		
Code: ZZ_2431 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 2 Type: Dent(s), ding(s), scratch(es)	Description: Bath 2: center support trim piece under sink needs to be replaced, top drawers may need to be adjusted Inside back center panel needs touch up Inside doors need touch up	Incomplete
Code: ZZ_2437 Category: Cabinets Partner: Cabinet Connection	Location: Laundry Room Type: Part missing	Description: Laundry room - decking under sink is broken off	Incomplete
Code: ZZ_2442 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Kitchen cabinets: left of cook top Line in crown, inside upper doors have cracks, inside doors of lower cabinets have cracks on back of doors	Incomplete
Code: ZZ_2443 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Kitchen: right of stove - upper cabs inside the doors cracks	Incomplete
Code: ZZ_2444 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Kitchen: crown above the stove has a lone and uppers above the stove inside cabinet doors have cracks	Incomplete
Code: ZZ_2446 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Kitchen lower cabinets on right side of stove have cracks inside the doors Line in crown as well	Incomplete
Code: ZZ_2447 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Kitchen island cabinets - few cracks inside far right side cabinet Scratches and cracks inside cabinet under sink	Incomplete
Code: ZZ_2448 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Kitchen cabinets: right side of the pantry: uppers have cracks inside the doors Lowers have some cracks inside and on top	Incomplete

All Defects	Lot 144/Tract 0273		
Code: ZZ_2449 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Dent(s), ding(s), scratch(es)	Description: Kitchen cabinet above fridge - has some cracks inside the door	Incomplete
Code: ZZ_2451 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Dent(s), ding(s), scratch(es)	Description: Master bath cabinet vanity Center support trim under sinks need to be replaced under both sinks. Left side inside the cabinet back and sides lots of big gouges and exposed nails	Incomplete
Code: ZZ_2452 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Dent(s), ding(s), scratch(es)	Description: Master bath trim under the counter has exposed nail heads need to be puttied	Incomplete
De Young Properties			
Code: ZZ_2419 Category: Builder Personnel Partner: De Young Properties	Location: Bedroom 4 Type:	Description: Bed 4 check inside th left side of closet upper corner by outlet for alarm Could there have been a roof leak? Water stain on wall	Incomplete
Code: ZZ_2424 Category: Plumbing Partner: De Young Properties	Location: Bathroom 3 Type:	Description: Bath 3 - few marks on the bath fitter surround	Incomplete
Code: ZZ_2433 Category: Builder Personnel Partner: De Young Properties	Location: Bathroom 2 Type:	Description: Bath 2 couple marks on surround of bath fitter	Incomplete
Donald P. Dick			
Code: ZZ_2436 Category: HVAC Partner: Donald P. Dick	Location: Entryway Type:	Description: Register at family entry next to laundry door is crooked	Incomplete

All Defects	Lot 144/Tract 0273		
Code: ZZ_2440 Category: HVAC Partner: Donald P. Dick	Location: Great Room Type:	Description: Thermostat on the wall in great room is crooked	Incomplete
Code: ZZ_2454 Category: HVAC Partner: Donald P. Dick	Location: Master Closet Type:	Description: Master closet register is not installed	Incomplete
Elia Painting			
Code: ZZ_2418 Category: Paint Partner: Elia Painting	Location: Bedroom 4 Type: Cleanup	Description: Bed 4 paint touch up throughout including inside the closet Caulk touch up all trim and windows Back of closet doors and hardware	Incomplete
Code: ZZ_2422 Category: Paint Partner: Elia Painting	Location: Bathroom 3 Type: Cleanup	Description: Bath 3: paint touch up needed inside various spots.	Incomplete
Code: ZZ_2427 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type: Cleanup	Description: Bed 3 paint touch up in various places around room and caulking touch up around trim and window Paint door to attic space	Incomplete
Code: ZZ_2428 Category: Paint Partner: Elia Painting	Location: Bedroom 3 Type:	Description: Bed 3: door trim has a couple chips and dents	Incomplete
Code: ZZ_2429 Category: Paint Partner: Elia Painting	Location: Bathroom 2 Type: Cleanup	Description: Paint touch up throughout upstairs hallway and stairwell Sent in base at stairwell	Incomplete
Code: ZZ_2434 Category: Paint Partner: Elia Painting	Location: Bedroom 2 Type: Cleanup	Description: Bed 2: finish paint touch up throughout and caulking touch up	Incomplete

All Defects	Lot 144/Tract 0273		
Code: ZZ_2438 Category: Paint Partner: Elia Painting	Location: Laundry Room Type: Cleanup	Description: Paint touch up in a few spots is wrong color	Incomplete
Code: ZZ_2439 Category: Paint Partner: Elia Painting	Location: Bathroom 2 Type: Cleanup	Description: Bath 2 paint touch up above shower is wrong sheen of paint	Incomplete
Code: ZZ_2450 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type: Chip/gouge/scratch	Description: Door way from master to master bath has chip	Incomplete
Code: ZZ_2455 Category: Paint Partner: Elia Painting	Location: Bathroom 1 Type: Cleanup	Description: Master bath - lots of touch up needed Two different colors and sheens on. The walls	Incomplete
Code: ZZ_2458 Category: Paint Partner: Elia Painting	Location: Exterior Type: Cleanup	Description: Finish paint touch up on exterior	Incomplete
Fenceworks			
Code: ZZ_2456 Category: Fence Partner: Fenceworks	Location: Exterior Type: Gate string missing/broken	Description: Install fence	Incomplete
Granite Mountain Stor	ne Design		
Code: ZZ_2453 Category: Solid Surface Partner: Granite Mountain Stone Design	Location: Bathroom 1 Type:	Description: Master bath - counter top back splash piece is missing	Incomplete

All Defects	Lot 144/Tract 0273				
Code: ZZ_2428 Category: Millwork Partner: Matthews Quality Construction	Location: Bedroom 3 Type:	Description: Bed 3: Attic door needs hardware	Incomplete		
Code: ZZ_2430 Category: Millwork Partner: Matthews Quality Construction	Location: Bathroom 2 Type:	Description: Bath 2 Install missing hardware on door	Incomplete		
Code: ZZ_2435 Category: Millwork Partner: Matthews Quality Construction	Location: Bedroom 2 Type:	Description: Bed 2 rehang closet doors	Incomplete		
Ohanians Drywall					
Code: ZZ_2425 Category: Drywall Partner: Ohanians Drywall	Location: Bathroom 3 Type: Texture issue	Description: Bath 3: couple spots drywall touch up near vanity wall	Incomplete		
Code: ZZ_2425 Category: Drywall Partner: Ohanians Drywall	Location: Bathroom 3 Type:	Description: Bath 3: couple spots drywall touch up near vanity wall	Incomplete		
Tri Valley Plastering	Tri Valley Plastering & Drywall				
Code: ZZ_2459 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type:	Description: Stucco touch up needed around exterior in several spots And above pop out above garage door	Incomplete		
True Frame					
Code: ZZ_2460 Category: Framing Partner: True Frame	Location: Exterior Type:	Description: check wood fascia under roof line above the main elterical panel Cracked and large gouge	Incomplete		

All Defects	Lot 144/Tract 0273		
Code: ZZ_2460 Category: Framing Partner: True Frame	Location: Exterior Type:	Description: check wood fascia under roof line above the main elterical panel Cracked and large gouge	Incomplete
Visalia Tile			
Code: ZZ_2445 Category: Tile Partner: Visalia Tile	Location: Kitchen Type:	Description: Kitchen counter back splash grout has cracks	Incomplete
Westech			
Code: ZZ_2420 Category: Electrical Partner: Westech	Location: Bedroom 4 Type:	Description: Bed 4- light switch in hall by bed 4 is missing a screw on bottom of outlet cover plate	Incomplete
Code: ZZ_2427 Category: Electrical Partner: Westech	Location: Bathroom 2 Type:	Description: Bath 2: missing vanity light	Incomplete
Code: ZZ_2457 Category: Electrical Partner: Westech	Location: Entryway Type:	Description: Missing light above front door at porch	Incomplete