De Young Properties

All Defects	Lot 33/Trac	Lot 33/Tract 6260		
Anlin Windows				
Code: ZZ_422 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Latch in multi gen not working for window	Incomplet	
Code: ZZ_425 Category: Windows Partner: Anlin Windows	Location: Type:	Description: Window in great room latch won't work	Incomplet	
Cabinet Connection				
Code: ZZ_420 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratches in laundry room on upper cabinets	Incomplet	
Code: ZZ_421 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Hole in bottom shelf under kitchen sink	Incomplet	
Code: ZZ_423 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Cabinet scratch on face of cabinets in multigen	Incomplet	
Code: ZZ_424 Category: Cabinets Partner: Cabinet Connection	Location: Type:	Description: Scribe missing in multi gen	Incomplet	
Everlast Paint				
Code: ZZ_430 Category: Paint Partner: Everlast Paint	Location: Type:	Description: Paint throughout home is terrible John mark and Brice have all been notified	Incomplet	

All Defects	Lot 33/Tract 6260			
Code: ZZ_429 Category: Solid Surface Partner: Granite Mountain Stone Design	Location: Type:	Description: Kitchen counter rust stained	Incomplete	
Ohanians Drywall				
Code: ZZ_428 Category: Drywall Partner: Ohanians Drywall	Location: Type:	Description: Drywall in master bath above shower	Incomplete	
Tile Interiors				
Code: ZZ_426 Category: Tile Partner: Tile Interiors	Location: Type:	Description: Grout crack bath 4	Incomplete	
Code: ZZ_427 Category: Tile Partner: Tile Interiors	Location: Type:	Description: Shelf in bath 2 shower missing Multi gen shower missing shelf	Incomplete	