De Young Properties

Lot 32/Tract 6100	Items: 24	CH Items: 3	Checklist Inspections: 95
84 Lumber			
Code: ZZ_155 Category: Windows Partner: 84 Lumber	Location: Rear Patio Type: Slider door to patio: Screens missing or damaged	Description: Missing slider screen	Incomplete
Cabinet Connection			
Code: B_022 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Rough finish on south master sink cabinet	Incomplete
Code: ZZ_157 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Scratches/chips/cracks/gouges in cabinets	Description: Black dot on south master bath cabinet	Incomplete
Code: ZZ_158 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Cabinet Hardware Issue	Description: Handle incorrectly installed	Incomplete
Code: ZZ_159 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Cabinet Hardware Issue	Description: Master cab handle not installed right	Incomplete
Code: ZZ_160 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Doors and drawers not square	Incomplete

Checklist Lot 32/Tract 6100 Items: 24 CH Items: 3 Inspections: 95 Code: ZZ 148 Location: Front Yard Category: Description: Large Landscaping Incomplete Type: Landscape not installed and/or there divot in grass are dead plants Partner: Landscape Connection Matthews Quality Construction Code: ZZ_163 Location: Bathroom 1 Category: Millwork Description: Missing casing and baseboards Incomplete Type: Door trim has chip, gash, gouge, cut Partner: Matthews in master bath too short near flooring or is missing **Quality Construction Quality Plumbing** Code: ZZ_164 Location: Bathroom 1 Description: Adjust Category: Plumbing CRITICAL sink plug. Hitting Type: Faucet, shower, tub, and/or toilet Incomplete backslash. Partner: Quality are not working Plumbing Code: ZZ 165 Location: Bathroom 1 Category: Plumbing Description: Hot water CRITICAL not working Incomplete Type: Hot water not working Partner: Quality Plumbing Simas Flooring & Design Code: ZZ 156 Category: Carpet / Location: Master Closet Description: Missing Hardwood / CRITICAL carpet in master Laminate Incomplete Type: Carpet is not installed closet Partner: Simas Flooring & Design Spence Fence Code: ZZ 145 Location: Backyard Category: Fence **Description: Splitting** Incomplete Type: Fence Boards or Posts board

Partner: Spence

Fence

cracked/warped/defective

Lot 32/Tract 6100	Items: 24	CH Items: 3	Checklist Inspections: 95	
Code: ZZ_146 Category: Fence Partner: Spence Fence	Location: Backyard Type: Fence Boards or Posts cracked/warped/defective	Description: Splitting board	Incomplete	
Code: ZZ_147 Category: Fence Partner: Spence Fence	Location: Backyard Type: Fence Boards or Posts cracked/warped/defective	Description: Splitting board	Incomplete	
Tri Valley Plastering & Drywall				
Code: F_005 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Inconsistent Fog coat	Description: Too much dirt in stucco and blotch	Incomplete	
Code: ZZ_154 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Inconsistent Fog coat	Description: Clean dirt along much of the bottom of the stucco.	Incomplete	
Westech				
Code: ZZ_153 Category: Electrical Partner: Westech	Location: Exterior Type: Light fixture, or pieces of light fixture, are missing	Description: Two missing light bulbs at coach lights.	Incomplete	
Code: ZZ_161 Category: Electrical Partner: Westech	Location: Bathroom 1 Type: Light fixtures, or pieces of light fixtures, are missing	Description: Missing lights at both vanities	Incomplete	