De Young Properties

Lot 352/Tract 0273	Items: 19	CH Items: 2	Checklist Inspections: 192
Anlin Windows			
Code: ZZ_976 Category: Windows Partner: Anlin Windows	Location: Great Room Type: Window missing a screen	Description: Missing screens on windows in whole gome	Incomplete
Cabinet Connection			
Code: ZZ_969 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Blemish on crown above fridge surround	Incomplete
Code: ZZ_970 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Drawer to the left of oven has paint coming off on the corner	Incomplete
Code: ZZ_971 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Cabinet door under island has paint coming on top edge	Incomplete
Code: ZZ_972 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Paint rubbed off on cabinet drawers to the right of oven	Incomplete
Code: ZZ_973 Category: Cabinets Partner: Cabinet Connection	Location: Kitchen Type: Cabinets have scratches, chips, and/or cracks	Description: Scratch on cabinet door right of microwave	Incomplete
Code: ZZ_977 Category: Cabinets Partner: Cabinet Connection	Location: Bathroom 1 Type: Issues with cabinet drawers and/or doors functionality	Description: Cabinet doors on left side vanity are uneven	Incomplete

Lot 352/Tract 0273	Items: 19	CH Items: 2	Checklist Inspections: 192	
Code: ZZ_981 Category: Plumbing Partner: Quality Plumbing	Location: Bathroom 2 Type: Defect(s) in Bath/Shower fitter/surround	Description: Rust stains on bottom of tub	Incomplete	
Tri Valley Plastering & Drywall				
Code: ZZ_982 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Inconsistent Fog coat	Description: Fog whole exterior of home inconsistent color	Incomplete	
Code: ZZ_983 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Nail showing on front left of home	Incomplete	
Code: ZZ_984 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Inconsistent Fog coat	Description: Stucco color around eve outlet back yard	Incomplete	
Code: ZZ_985 Category: Stucco Partner: Tri Valley Plastering & Drywall	Location: Exterior Type: Chip/crack/gouge	Description: Stucco chip by back yard outlet	Incomplete	
Visalia Tile				
Code: ZZ_974 Category: Tile Partner: Visalia Tile	Location: Great Room Type: Grout at tile is cracked, missing, wrong color, and/or needs touch-up	Description: Grout crack by back slider	Incomplete	