

WERCO ERP-MES

Werco Glossary

Employee Training Handout

Werco Manufacturing — precision manufacturing ERP & MES

AS9100D · ISO 9001 · CMMC Level 2

Generated 2026-06-09

Contents

1. Terms
2. User roles

Plain-language definitions for the terms you'll run into while using the Werco system. Terms are listed A to Z. The user roles are explained at the end.

Terms

Term	What it means
BOM (bill of materials)	The recipe for a part — the full list of materials, components, and quantities needed to build it.
CAR (corrective action report)	A record opened to fix the root cause of a recurring or serious problem so it doesn't happen again, not just to patch the one bad part.
CoC (certificate of conformance)	A supplier's signed document stating that the material or parts they shipped meet the requirements. Captured at receiving and often sent out with a shipment.
Dispatch score	A number the system uses to rank jobs in your queue so the most urgent work shows up first. It blends how overdue a job is, its priority, and its due date.
ECO (engineering change order)	A controlled, written change to a part, drawing, or how something is made. Tracked so everyone works from the latest approved version.
FAI (first article inspection)	A full, documented inspection of the first piece off a new or changed job to prove it meets the drawing before you run the rest.
Heat number	The supplier's batch identifier for a melt of metal, shown on the material cert. Captured at receiving so the exact material batch can be traced to the parts made from it.
Kiosk mode	The simplified, big-button shop-floor screen built for shared touchscreens at the machine. Operators are sent here automatically after signing in.
KPI (key performance indicator)	A headline number that tells you how something is doing at a glance — for example active work orders, due today, overdue, or open NCRs. The Dashboard and Analytics screens show KPIs as cards.
Lot / Serial	Two ways to track material. A lot is a batch of identical parts tracked as a group; a serial number tracks one single unique part. Both let you trace where material came from and where it went.
Make vs. buy part	Whether a part is built here in-house ("make") or purchased from a supplier ("buy"). This affects whether it gets a work order or a purchase order.
MRP (material requirements planning)	A calculation that looks at what you need to build versus what's on hand, finds shortages, and suggests purchase orders to cover them.
NCR (non-conformance report)	A record raised when a part or material doesn't meet the requirement (wrong dimension, damage, defect). It documents the issue and how it was resolved.
OEE (overall equipment)	A score for how productive a machine or work center is, combining how much it's running, how fast, and how much good output it makes.

Term	What it means
effectiveness)	
Operation	A single step in making a part — for example cut, bend, weld, or inspect. A job is a sequence of operations done in order.
Part revision	The version of a part or drawing (Rev A, Rev B, and so on). When a part changes, a new revision is created so older records stay accurate.
Priority (P1–P10)	The urgency ranking on a work order. P1 is the most urgent; P10 is the least. Higher-priority jobs rise to the top of the queue.
PO (purchase order)	An official order sent to a supplier to buy materials, parts, or services.
QMS (quality management system)	The set of standards, procedures, and records that keep quality consistent and auditable (AS9100D / ISO 9001). The QMS Standards screen is your in-system reference for it.
Quote / RFQ	An RFQ (request for quote) is a customer asking what a job would cost; a quote is the priced answer you send back.
Routing	The ordered list of operations and work centers that defines how a part is made from start to finish.
SPC (statistical process control)	Tracking measurements over time on charts to spot when a process is drifting out of spec before it makes bad parts.
Traceability	The ability to follow a part's full history — what material (lot/serial) went into it, which jobs and operations it passed through, and where it shipped.
Traveler	The printed routing packet that travels with a job through the shop, listing the operations, instructions, and sign-offs for that work order.
Work center	A machine, station, or area where operations happen (for example a press brake, a CNC mill, the paint booth, or inspection).
Work order (WO)	The instruction to build a specific part in a specific quantity by a due date. It carries the BOM, routing, and operations for that job. Often shortened to WO (and WO # for its number).

User roles

Your role decides what you can see and do. All roles only see data for your own company.

Role	What it's for
platform_admin	Werco oversight. Can switch between companies and view across them (read-only). Not a day-to-day shop role.
admin	Full access for one company, including Admin Settings and user management. Usually IT or a system administrator.
manager	Broad control over operations plus approvals. Cannot change admin-only settings.
supervisor	Runs shop execution and planning, with limited user and admin controls. Shift supervisors and team leads.
operator	Executes work on the floor — start, hold, resume, and complete operations and record production.
quality	Handles inspections and quality approvals (NCRs, CARs, FAIs, and related sign-offs).
shipping	Handles shipping operations — preparing shipments, marking them shipped, and packing slips.
viewer	Read-only access. For auditors, executives, and guests who need to look but not change anything.