


The angle you want to use is physically difficult to bend, the shape you present in the image will be difficult to achieve.

## Option 2



used industrial materials: The same as in option 1



This option is the best because it is easier to fold but it has to be done in 2 parts.

JE

