`greenerthumb` Requirements

1. Each hardware component must be optional.
2. Sense:
   a. Air temperature.
   b. Soil moisture.
3. Publish sensed data on a connected network.
4. Log sensed data from the network into rotating logs.
5. Plot sensed data from the network.
6. Include useful log processors.
7. Provide install tools.
8. Handle errors consistently.