




Implement your controller here







Draw three circles with a radius of 0.1m that are aligned on a line. There should be zero or grader distances between them. Trajectory from one cycle to next needs to be planned, too.

Reference






Tracking error




Peak error between t=1~10 is <3cm. RMSE is XXX cm


Joint torques



This particular sample does NOT satisfy the requirements.



Reproduced



Peak error between t=1~10 is **4.4 cm**. RMSE between t=1~10 is **1.42 cm**.

Joint torques

