

Removing Small Geometric Entities with Repair

Introduction

In this example, the Parasolid[®] file of a wheel rim contains a few small details, which are not removed during import, since they fall outside the default import tolerance. The stepby-step instructions demonstrate one way to locate and remove these features using the Repair operation. The general workflow is:

- Import the file.
- Create a mesh for quick examination of the geometry.
- Measure the size of the features you would like to remove.
- · Repair the object.
- Create a new mesh for comparison.

For the step-by-step instructions of this tutorial, see the book $Introduction\ to\ LiveLink^{\text{TM}}$ for PTC® Creo® Parametric™.

Application Library path: LiveLink_for_PTC_Creo_Parametric/Tutorials, CAD Import/wheel rim repair