Module 1: Getting Started with 3D CAD

Lesson 1: Welcome and System Orientation

Welcome to 3D CAD Modeling. In this course you will learn core solid modeling workflows.

Save the completed model to your project workspace before continuing to the next exercise.

Module 1: Getting Started with 3D CAD

Lesson 2: Sketch Plane Selection

Select Front Plane, Top Plane, or Right Plane from the design tree to establish a 2D sketch plane. Ensure grid snap settings match your engineering tolerance requirements.

Module 2: Sketching Fundamentals

Lesson 3: The Sketch Environment & Toolbar

Open Sketch and select the Sketch toolbar shown in Figure 2-1 below.

The Sketch toolbar contains essential drawing commands such as Line, Circle, Rectangle, and Spline.

Click the Sketch toolbar button to initiate profile creation and observe tool parameters.

[Screenshot / Figure 2-1: Sketch Toolbar Layout (SOLIDWORKS 2024 UI)]

Visual capture illustrating old Sketch toolbar icons, button arrangements, and floating command ribbon.

Caption: Figure 2-1 shows the standard Sketch toolbar layout for drawing entities.

Notice how the drawing tools are grouped together for rapid access during sketching.