

Blynk Widget

- Temperature Gauge 0-60 /pin/ C (Green) V5
- Humidity Gauge 0-100 /pin/ % (Green) V6
- Step H Temperature 0-100 (Red) V24
- Set H Range (Temp.) 0-50 (Green) V25
- Set H Humidity 0-100 (Blue) V26
- Set H Range (Humidity) 0-50 (Green) V27
- LED Power (Red) V10
- LED Auto (Green) V11
- Button Plug ON: On OFF: Off (Red) V1
- Button Mode ON: AUTO OFF: Manual (Blue) V2
- Button Temperature (Blue) ON: Cool OFF: Heat V20
- Humidity (Blue) ON: Moisture OFF: Dehumidifier V21
- Step V Option 0-2 Loop (Green) V22
- Button Reset Board (Orange) ON: Reset V23

