




Types of imbalance



+ Bent shaft, which causes imbalance during rotation

rotor.zone

BENT SHAFT



- Bent shaft problems cause high axial vibration
- 1X RPM dominant if bend is near shaft center
- 2X RPM dominant if bend is near shaft ends
- Phase difference in the axial direction will tend towards 180° difference

The placement of the sensors

We need 4 sensors :

2 sensors on each bearing (we have 2 bearings),
one of them to collect axial vibration,
and the second to collect the radial vibration

The type of collected data

Data is collected from the Pizo-velocity sensor, so the data is the velocity of the sensor while it is vibrating.